

# HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

### PAINTERSVILLE BRIDGE

HAER CA-2295

(Bridge No. 24-53)

Spanning the Sacramento River at California State Highway 160

Courtland vicinity

Sacramento County

California

Note: The negatives received by HAER were dirty, scratched and damaged. 16 negatives were damaged copy negatives. The copy negatives were removed from the photographic documentation and placed in the field notes for this survey.

### INDEX TO BLACK AND WHITE PHOTOGRAPHS

CA-2295-1      Aerial view, taken from above. Original photograph located in California Department of Transportation (CALTRANS) Engineering Services Division, Structure Design Services & Earthquake Engineering, Office of Photogrammetry, Sacramento, California. General view of bridge in relationship to its surrounding environment

Don Tateishi & Ed Anderson, Photographers, October 2002

CA-2295-2      Distant view of north side of bridge, looking southwest from State Highway 160

Don Tateishi, Photographer, August 2004

CA-2295-3      Distant view to northern side of bridge, looking southeast from county road

Don Tateishi & Ed Anderson, Photographers, October 2002

CA-2295-4      General view of south side of bridge, view looking northwest from county road

CA-2295-5      General view of south side of bridge, view looking northeast from State Highway 160

CA-2295-6      General view of approach to bridge, looking west

CA-2295-7      General view of approach to bridge, looking east

CA-2295-8      Detail view of structural elements: steel pony truss, eastern span, looking north

- CA-2295-9 Detail view of structural elements: pylons, piers, steel framing and trusses, looking northwest from south side of bridge
- CA-2295-10 Detail view of structural elements: west concrete counterweight, steel truss and piers, looking northeast from south side of bridge. Note traffic gate in upright position
- CA-2295-11 Detail view of north wall on east end approach, portal and concrete wing wall, looking northwest. Note that the wing wall is the same as opposite wall.
- CA-2295-12 Detail view of north side metal railing on the west-end approach, portal and wing wall, looking northeast
- CA-2295-13 Detail view of timber wheel guards and metal trellis railings on eastern span of bridge, looking northwest
- CA-2295-14 Detail view of bridge deck and traffic gates in downward position, looking west
- CA-2295-15 Detail view of traffic lights and signals located on west end of bridge, looking east
- CA-2295-16 Detail view of sanitation holding tanks and piping, railing and timber wheel guard, looking southwest from opposite the bridge control operator's house
- CA-2295-17 Detail view of fog bell, looking northwest
- CA-2295-18 Detail view of air horns located above the bridge control operator's house, view of stairs to gear house located above truss, looking east
- CA-2295-19 Distant view of bridge control operator's house, looking southeast from western bank of Sacramento River
- CA-2295-20 General view of north façade of bridge control operator's house, looking southwest from eastern bank of Sacramento River
- CA-2295-21 General view of south façade of bridge control operator's house, looking northwest from western bank of Sacramento River
- CA-2295-22 General view of south façade of bridge control operator's house, looking north
- CA-2295-23 General view of east façade of bridge control operator's house, looking west
- CA-2295-24 General view of west façade of bridge control operator's house, looking east
- CA-2295-25 Detail view of exterior architectural elements: view of west entryway and window on south façade of bridge control operator's house, looking north
- CA-2295-26 Detail view of exterior architectural elements: view of doors located on south façade of bridge control operator's house, looking north

- CA-2295-27 General view of walkway to bridge control operator's house located along the north side of bridge, looking southwest from the eastern bank of the Sacramento River
- CA-2295-28 Detail view of walkway to bridge control operator's house, looking west
- CA-2295-29 General view of west half of the interior of bridge control operator's house, looking west toward bridge controls, from center of control house
- CA-2295-30 General view of east half of the interior of bridge control operator's house, looking east toward air compressor and engine generator from center of control house
- CA-2295-31 Detail view of interior of bridge control operator's house, view of engine generator and air compressor, looking east
- CA-2295-32 Detail view of interior of bridge control operator's house, view of electrical panel, looking southwest
- CA-2295-33 Detail view of interior of bridge control operator's house, view of engine generator, looking west
- CA-2295-34 Detail view of interior of bridge control operator's house, view of Westinghouse control panel dated 1940, looking west
- Don Tateishi, Photographer, May 2004
- CA-2295-35 Detail view of east façade of gear house located above the western truss and deck, looking west from deck