

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

U.S. NAVAL BASE, PEARL HARBOR, NAVAL HOUSING AREA PEARL CITY
PENINSULA, UYEHARA HOUSE AND GARAGE HABS No. HI-358-B
(Facility Nos. 637 and 639)
1038 Ashley Avenue
Pearl Harbor
Honolulu County
Hawaii

David Franzen, Photographer

July 2000

- HI-358-B-1 FACILITY 639. OBLIQUE OF GARAGE, WITH HOUSE (FACILITY 637) IN BACKGROUND. VIEW FACING WEST-NORTHWEST.
- HI-358-B-2 FACILITY 639. FRONT OF GARAGE. VIEW FACING NORTH-NORTHWEST.
- HI-358-B-3 FACILITY 637. EAST SIDE OF HOUSE, AS SEEN FROM PATH NEAR GARAGE. VIEW FACING
- HI-358-B-4 FACILITY 637. FRONT OF HOUSE, AS SEEN FROM YARD. VIEW FACING WEST-SOUTHWEST.
- HI-358-B-5 FACILITY 637. OBLIQUE OF FRONT AND WEST SIDE OF HOUSE WITH NEIGHBORING HOUSE (FACILITY 636) BEYOND ON RIGHT. VIEW FACING EAST-SOUTHEAST.
- HI-358-B-6 FACILITY 637. LAVA ROCK PILLARS ON BOUNDARY OF FACILITIES 636 AND 637. VIEW FACING NORTH-NORTHEAST.
- HI-358-B-7 FACILITY 637. OBLIQUE OF REAR, SHOWING KITCHEN ENTRY AT LEFT. VIEW FACING NORTH-NORTHEAST.
- HI-358-B-8 FACILITY 637. INTERIOR OF LIVING ROOM, LOOKING TOWARD FIREPLACE. ENTRY DOOR TO LEFT. VIEW FACING SOUTH-SOUTHEAST.
- HI-358-B-9 FACILITY 637. INTERIOR OF DINING ROOM, LOOKING TOWARD LIVING ROOM. ENCLOSED LANAI VISIBLE THROUGH WINDOWS. VIEW FACING NORTH-NORTHEAST.
- HI-358-B-10 FACILITY 637. INTERIOR OF KITCHEN, LOOKING TOWARD DINING ROOM. VIEW FACING NORTH.
- HI-358-B-11 FACILITY 637. MASTER BATHROOM, SHOWING ORIGINAL TILE AND PORCELAIN FIXTURES. VIEW FACING NORTH-NORTHEAST.
- HI-358-B-12 FACILITY 637. INTERIOR OF SMALL BEDROOM, SHOWING ITS OWN EXTERIOR DOOR. VIEW FACING NORTH-NORTHWEST.