

HISTORIC AMERICAN ENGINEERING RECORD

HAER  
ID,  
6-SHEL.V,  
1-

Index to Photographs

Snake River Valley Irrigation District  
East side of the Snake River  
Shelley vicinity  
Bingham and Bonneville Counties  
Idaho

HAER No. 1D-10

NOTE: Photographs were taken by Gene Bonham, photographer, March 1986

- ID-10-1 SNAKE RIVER VALLEY IRRIGATION DISTRICT DAM, VIEW OF NORTH ELEVATION OF INTAKE ON EAST SIDE OF DAM
- ID-10-2 SNAKE RIVER VALLEY IRRIGATION DISTRICT DAM, PHOTOGRAPHIC COPY OF DRAWING, PLAN, SHEET 5 OF 5, 1924 (on file at the Idaho State Office of Water Resources, Boise, Idaho)
- ID-10-3 SNAKE RIVER VALLEY IRRIGATION DISTRICT, PHOTOGRAPHIC COPY OF DRAWING, PROFILE AND ALIGNMENT OF DAM ACROSS WEST CHANNEL OF SNAKE RIVER, SHEET 3 OF 5, 1924 (on file at the Idaho State Office of Water Resources, Boise, Idaho)
- ID-10-4 SNAKE RIVER VALLEY IRRIGATION DISTRICT, PHOTOGRAPHIC COPY OF DRAWING, PROPOSED SECTION OF DIVERSION DAM ACROSS SNAKE RIVER, SHEET 1 OF 5, 1924 (on file at the Idaho State Office of Water Resources, Boise, Idaho)
- ID-10-5 SNAKE RIVER VALLEY IRRIGATION DISTRICT DAM, VIEW OF SOUTH ELEVATION, EAST END
- ID-10-6 DAM AND MAIN CANAL HEADGATE, VIEW OF SOUTH ELEVATION
- ID-10-7 MAIN CANAL HEADGATE, VIEW OF SOUTH ELEVATION
- ID-10-8 MAIN CANAL HEADGATE, DETAIL VIEW OF GATES AND ABUTMENT, SOUTH ELEVATION
- ID-10-9 MAIN CANAL HEADGATE, VIEW OF NORTH ELEVATION
- ID-10-10 VIEW OF HEADGATE WINCHES, 'WALKER MFC CO. DENVER, COLO.'
- ID-10-11 MAIN CANAL HEADGATE, 'MAY 1ST, 1913' INSPECTION IN CONCRETE
- ID-10-12 VIEW OF MAIN CANAL AND WASTEGATE ABUTMENTS IMMEDIATELY SOUTH OF THE HEADGATE

Snake River Valley Irrigation  
District  
HAER No. ID-10  
Index to Photographs  
(Page 2)

- ID-10-13 WASTEGATE, VIEW OF WEST ELEVATION IMMEDIATELY SOUTH OF HEADGATE
- ID-10-14 VIEW OF MAIN CANAL AND FOOT BRIDGE, NE 1/4 OF SECTION 3, T1N, R37E
- ID-10-15 VIEW, LOOKING NORTH, OF MAIN CANAL NEAR STATE HIGHWAY NO. 26 BRIDGE