

HAMMOND-HARWOOD HOUSE
19 Maryland Ave and King George Street
Annapolis
Anne Arundel County
Maryland

HABS No. MD-251

HABS
MD,
2-ANNA,
18-

NOTE: Photographs numbered MD, 2-ANNA, 18-1, -2, -4 through -12
are in the PAEAA Collection.

This note is not official HABS/HAER documentation.

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MD,
2-ANNA,
18-

Addendum to

Hammond-Harwood House
19 Maryland Avenue and Prince George Street
Annapolis
Anne Arundel County
Maryland

HABS No. MD-251

Photographs MD-251-1 through MD-251-8 were transmitted to the Library of Congress in 1936-1937.

Ronald Comedy, Photographer February 8, 1970

- MD-251- ~~1~~²⁰ MAIN ELEVATION
MD-251- ~~10~~²¹ MAIN ELEVATION, DETAIL OF ENTRANCE
MD-251- ~~11~~²² MAIN ELEVATION, DETAIL OF ENTRANCE, DETAIL OF PEDIMENT AND
FRIEZE (UNDER RESTORATION)
MD-251- ~~12~~²³ MAIN ELEVATION, DETAIL OF ENTRANCE PEDIMENT (UNDER RESTORATION)
MD-251- ~~13~~²⁴ MAIN ELEVATION, DETAIL OF ENTRANCE DECORATION, OVOLO AND KEY
BLOCK (UNDER RESTORATION)
MD-251- ~~14~~²⁵ MAIN ELEVATION, DETAIL OF ENTRANCE DECORATION, FLOWER FESTOON
FROM SPANDREL (UNDER RESTORATION)
MD-251- ~~15~~²⁶ MAIN ELEVATION, DETAIL OF ENTRANCE DECORATION, CAPITAL VOLUTES
(UNDER RESTORATION)
MD-251- ~~16~~²⁷ MAIN ELEVATION, DETAIL OF ENTRANCE DECORATION, ANNULET (UNDER
RESTORATION)
MD-251- ~~17~~²⁸ REAR ELEVATION

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
MD,
2-ANNA,
1B-

ADDENDUM TO
HAMMOND-HARWOOD HOUSE
19 Maryland Avenue and King George Street
Annapolis
Anne Arundel County
Maryland

HABS No. MD-251

MD-251-1 through MD-251-17 were transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Ronald Comedy, Photographer, February 1970

MD-251-²⁴18 (CT)

MAIN ELEVATION, DETAIL OF ENTRANCE DECORATION, FLOWER FESTOON FROM
SPANDREL (UNDER RESTORATION)

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:

HAMMOND-HARWOOD HOUSE

19 Maryland Avenue & King George Street

Annapolis

Anne Arundel County

Maryland

HABS MD-251

INDEX TO BLACK AND WHITE PHOTOGRAPHS

James W. Rosenthal, photographer, July 2006

MD-251-29	Perspective view from north/northeast.
MD-251-30	Perspective view from northwest.
MD-251-31	Detail of door from north.

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:

HABS MD-251

HAMMOND-HARWOOD HOUSE

19 Maryland Avenue & King George Street

Annapolis

Anne Arundel County

Maryland

Photograph Nos. HABS MD-251-1 through HABS MD-251-31 were previously transmitted to Library of Congress.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

James W. Rosenthal, photographer, August 2011

MD-251-32	Perspective view showing the south (rear) of the house and the garden from southwest
MD-251-33	Elevation view of the center section of south (rear) facade
MD-251-34	Perspective view showing the rear of the house and the garden from southeast
MD-251-35	Detail view of jib door on south (rear) facade from southwest
MD-251-36	Elevation view of jib door on south (rear) facade
MD-251-37	Elevation view of jib door on south (rear) facade, with scale
MD-251-38	Elevation of the south (rear) facade of the east hyphen, with scale
MD-251-39	View from the front entrance looking north through open doors
MD-251-40	View of entrance hall from south
MD-251-41	View of entrance hall from north looking through to jib-door on south wall of the dining room
MD-251-42	Perspective view of dining room from southwest corner
MD-251-43	Perspective view of mantle in dining room from southwest

HAMMOND-HARWOOD HOUSE

HABS MD-251

INDEX TO PHOTOGRAPHS

Page 5

- MD-251-44 Detail view of jib-door, hall door, and crown molding in southwest corner of the dining room from northeast
- MD-251-45 View of first floor northwest room or Study from northeast corner
- MD-251-46 View of first floor, northeast room or Best Bedroom from northwest corner
- MD-251-47 View of first floor stair hall from northeast
- MD-251-48 View of second floor stair hall from north
- MD-251-49 View of second floor southwest room or study chamber from south
- MD-251-50 View of second floor southeast Ballroom/withdrawing room from southwest corner
- MD-251-51 View of second floor northeast bed chamber from northwest corner
- MD-251-52 View of uncovered roof structure on west wing from south. Note that rafters are nailed rather than notched into false plate and collar beams were added later and nailed into the rafters
- MD-251-53 Detail view of uncovered roof joinery on west wing from south, showing rafter ends and false plate
- MD-251-54 Detail view of uncovered roof joinery on southeast corner of west wing. Note corner bracing and outrigger beneath the false plate to carry overhanging cornice.
- MD-251-55 Detail view of uncovered roof joinery under the eaves on west wing. Note from center back, notches in the sill to hold outriggers in place.
- MD-251-56 Detail view of west wing, south facade oval window and bricks scored to resemble mortared joints.