


# HISTORIC AMERICAN BUILDINGS SURVEY

## Index to Photographs

U.S. Customs Service Port of Roosville,  
 Main Port Building  
 U.S. Highway 93 immediately south of U.S.-Canada border  
 Eureka vicinity  
 Lincoln County  
 Montana

HABS No. MT-110-A

Clayton B. Fraser, Fraserdesign, photographer, October 2001



Site Plan taken from Approach Plan by General Services Administration

- MT-110-A-1** GENERAL VIEW OF COMPLEX, SHOWING MAIN PORT BUILDING AT RIGHT BACKGROUND. VIEW TO NORTHWEST.
- MT-110-A-2** EAST FRONT OF BUILDING, WITH VEHICLE INSPECTION IN FOREGROUND. VIEW TO NORTHWEST.

- MT-110-A-3 EAST FRONT AND NORTH SIDE OF BUILDING. VIEW TO WEST.
- MT-110-A-4 DETAIL OF CENTER SECTION OF EAST FRONT OF BUILDING. VIEW TO WEST.
- MT-110-A-5 NORTH SIDE AND EAST FRONT OF BUILDING. VIEW TO SOUTHWEST.
- MT-110-A-6 WEST REAR AND NORTH SIDE OF BUILDING. VIEW TO SOUTHEAST.
- MT-110-A-7 WEST REAR AND SOUTH SIDE OF BUILDING. VIEW TO EAST.
- MT-110-A-8 DETAIL OF CENTER SECTION OF WEST REAR OF BUILDING. VIEW TO EAST.
- MT-110-A-9 SOUTH SIDE AND EAST FRONT OF BUILDING. VIEW TO NORTH.
- MT-110-A-10 EAST FRONT AND SOUTH SIDE OF BUILDING. VIEW TO NORTHWEST.
- MT-110-A-11 DETAIL OF FRONT OF BUILDING AND INSPECTION CANOPY. VIEW TO NORTH.
- MT-110-A-12 DETAIL OF CENTER SECTION OF EAST FRONT OF BUILDING. VIEW TO NORTH.
- MT-110-A-13 DETAIL OF WINDOW ON CENTER SECTION OF EAST FRONT OF BUILDING. VIEW TO WEST.
- MT-110-A-14 DETAIL OF CORNERSTONE ON CENTER SECTION OF EAST FRONT OF BUILDING. VIEW TO WEST.
- MT-110-A-15 INTERIOR VIEW OF BASEMENT BOILER ROOM. VIEW TO NORTHEAST.
- MT-110-A-16 INTERIOR VIEW OF BASEMENT MACHINE ROOM. VIEW TO NORTH.
- MT-110-A-17 INTERIOR VIEW OF FIRST FLOOR OFFICE IN NORTH FRAME SECTION OF BUILDING. VIEW TO SOUTH.
- MT-110-A-18 INTERIOR VIEW OF FIRST FLOOR OFFICE IN NORTH FRAME SECTION OF BUILDING. VIEW TO SOUTHWEST.
- MT-110-A-19 INTERIOR VIEW OF FIRST FLOOR HOLDING ROOM IN CUSTOMS PORTION OF CENTER SECTION OF BUILDING. VIEW TO WEST.
- MT-110-A-20 INTERIOR VIEW OF GARAGE IN SOUTH FRAME WING OF BUILDING. VIEW

- TO SOUTHWEST.
- MT-110-A-21** INTERIOR VIEW OF FIRST FLOOR INS OFFICE IN CENTER SECTION OF BUILDING, LOOKING TOWARD CUSTOMS SECTION. VIEW TO NORTHEAST.
- MT-110-A-22** INTERIOR VIEW OF FIRST FLOOR INS OFFICE IN CENTER SECTION OF BUILDING, WITH STAIRWAY AT RIGHT. VIEW TO SOUTHWEST.
- MT-110-A-23** INTERIOR DETAIL OF FIRST FLOOR STAIRWAY IN CENTER SECTION OF BUILDING. VIEW TO SOUTHWEST.
- MT-110-A-24** INTERIOR DETAIL OF SECOND FLOOR STAIRWAY IN CENTER SECTION OF BUILDING. VIEW TO SOUTHWEST.
- MT-110-A-25** INTERIOR VIEW OF SECOND FLOOR CORRIDOR IN CENTER SECTION OF BUILDING. VIEW TO NORTHEAST.
- MT-110-A-26** INTERIOR VIEW OF SECOND FLOOR INS DETENTION CELL IN CENTER SECTION OF BUILDING. VIEW TO NORTHWEST.