

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

MILLTOWN BRIDGE

HAER MT-134

(Bonner Bridge)

(Blackfoot Bridge)

Spanning the Blackfoot River on Anaconda Street

Milltown

Missoula County

Montana

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Kristi Hager, photographer, March 2007

| | |
|-----------|--|
| MT-134-1 | Overview; southwest side; view to northeast |
| MT-134-2 | Overview; northeast side; view to southwest |
| MT-134-3 | Three-quarters view; southwest side; view to north |
| MT-134-4 | Southeast portal; view to northwest |
| MT-134-5 | Three-quarters view; northeast side; view to south |
| MT-134-6 | Three-quarters view; northeast side; view to west |
| MT-134-7 | Northwest portal; view to southeast |
| MT-134-8 | Detail; dedication plate; view to northwest |
| MT-134-9 | Detail; pier no. 2 and underside of deck; view to north-northwest |
| MT-134-10 | Detail; pier no. 2 and underside of deck; view to west-northwest |
| MT-134-11 | Detail of sidewalk, truss, and lattice guardrail; southeast side; view to northwest |
| MT-134-12 | Detail of truss members, struts and deck; view to north |
| MT-134-13 | Detail of pier no. 1 and underside of approach span no. 1 and span no. 1; view to east |
| MT-134-14 | Detail of concrete guardwall on approach span no. 1; northeast side; view to north |