

HABS  
NM,  
1-ALBU,  
5-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Alvarado Hotel  
First Street  
Albuquerque  
Bernalillo County  
New Mexico

HABS No. NM-123

Fred Mang, Jr., Photographer October, 1969

- NM-123-1 LOOKING NORTHWEST FROM LEAD AVENUE OVERPASS. HOTEL ON RIGHT, AT & SF STATION ON LEFT
- NM-123-2 WEST SIDE, FROM CORNER OF FIRST STREET AND SILVER AVENUE
- NM-123-3 WEST SIDE, FROM CORNER OF FIRST STREET AND GOLD AVENUE (Original arcade on this side was blocked ca. 1934 to create bar and offices. High wall on left enclosed outdoor bar.)
- NM-123-4 EAST FRONT, ENTRANCE FROM STATION PLATFORM TO ARCADE WHICH LEADS AROUND CENTRAL PATIO TO HOTEL
- NM-123-5 CENTRAL PATIO, LOOKING NORTHWEST
- NM-123-6 CENTRAL PATIO, LOOKING NORTHWEST
- NM-123-7 CENTRAL PATIO, LOOKING NORTHEAST. PATIO IN FRONT OF DINING ROOM.
- NM-123-8 CENTRAL PATIO, LOOKING NORTHEAST
- NM-123-9 CENTRAL PATIO, LOOKING SOUTHEAST
- NM-123-10 CENTRAL PATIO, LOOKING SOUTHWEST
- NM-123-11 NORTH PATIO, FROM RAILROAD PLATFORM LOOKING WEST. (West and north wings and this patio constructed 1922)
- NM-123-12 NORTH PATIO, DETAIL OF FOUNTAIN AND DOORWAY
- NM-123-13 NORTH WING, EAST END. (Constructed 1922.)
- NM-123-14 NORTH PATIO, DETAIL OF LION'S HEAD FOUNTAIN SPOUT
- NM-123-15 CENTRAL PORTION OF HOTEL FROM RAILROAD PLATFORM NEAR NORTH END OF SOUTH PATIO, LOOKING NORTHWEST
- NM-123-16 SOUTH PATIO, NORTHWEST CORNER, IN FRONT OF LUNCH ROOM
- NM-123-17 SOUTH PATIO AND ARCADE IN FRONT OF INDIAN BUILDING AND LUNCH ROOM
- NM-123-18 INDIAN BUILDING, SOUTH FRONT, FROM STATION PLATFORM, LOOKING NORTHWEST

ALVARADO HOTEL  
HABS No. NM-123 (Page 2)  
Index to Photographs

- NM-123-19 INDIAN BUILDING, SOUTH FRONT (Constructed 1922)
- NM-123-20 INDIAN BUILDING, SOUTH FRONT, ENTRANCE
- NM-123-21 INDIAN BUILDING, SOUTH FRONT, ENTRANCE DETAIL
- NM-123-22 ARCADE ON EAST SIDE OF BUILDING, IN FRONT OF INDIAN BUILDING AND LUNCH ROOM
- NM-123-23 LOBBY, STAIRCASE TO UPPER FLOORS
- NM-123-24 DINING ROOM, FIREPLACE (Room remodeled 1922)
- NM-123-25 DINING ROOM, WINDOWS
- NM-123-26 LUNCH ROOM
- NM-123-27 LUNCH ROOM, DETAIL OF COPPER-FRAMED PASTRY BOXES AND ICE BOXES
- NM-123-28 1902 BAR, DETAIL OF TILES AT ENTRANCE. (Bar converted to lounge and card room in 1922; work shown is of that date.)
- NM-123-29 1902 BAR, TILE AND WOODEN GRILL
- NM-123-30 1902 BAR, DETAIL OF WOODWORK AND TILE AT ENTRANCE
- NM-123-31 1902 BAR, FIREPLACE
- NM-123-32 1902 BAR, DETAIL OF FIREPLACE
- NM-123-33 1902 BAR, WINDOWS WITH COPPER MULLIONS