

HABS
NM
16-CROPO.V,
2B-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Indian Creek, Casa Cielo
Chaco Outliers
Indian Creek
Crownpoint Vicinity
McKinley County
New Mexico

HABS No. NM-179-B

Documentation: 25 photographs

Robert Lyon, Photographer, June 1994

- NM-179-B-1 DISTANT VIEW, VIEW TOWARDS NORTHWEST
- NM-179-B-2 EAST WALL, VIEW TOWARDS WEST
- NM-179-B-3 SOUTH WALL AT LEFT, EAST WALL AT RIGHT, VIEW TOWARDS NORTHWEST
- NM-179-B-4 SOUTH WALL, VIEW TOWARDS NORTH
- NM-179-B-5 SOUTH WALL AT RIGHT, WEST WALL REMAINS AT LEFT, VIEW TOWARDS NORTHEAST
- NM-179-B-6 WEST WALL REMAINS, VIEW TOWARDS EAST
- NM-179-B-7 EAST WALL, NORTH ELEVATION, WINDOW VISIBLE AT LEFT CENTER
- NM-179-B-8 WINDOW DETAIL, EAST WALL
- NM-179-B-9 EAST WALL, SOUTH ELEVATION, VIEW TOWARDS WEST
- NM-179-B-10 SOUTH WALL, EAST ELEVATION, VIEW TOWARDS NORTH
- NM-179-B-11 SOUTH WALL, WEST ELEVATION, VIEW TOWARDS NORTH

- NM-179-B-12 NORTH WALL, VIEW TOWARDS SOUTHEAST
- NM-179-B-13 SOUTHEAST CORNER OF SITE, VIEW OF SOUTH WALL
TOWARDS WEST, POTSHARDS
- NM-179-B-14 SOUTH WALL FROM SOUTHEAST CORNER OF SITE, KIVA AT
UPPER RIGHT
- NM-179-B-15 INTERIOR LAYOUT, KIVA AT LEFT, VIEW TOWARDS
NORTHWEST
- NM-179-B-16 VIEW FROM SOUTHEAST CORNER OF SITE TOWARDS NORTH,
EAST WALL AT RIGHT
- NM-179-B-17 INTERIOR PASSAGEWAY, VIEW FROM EAST WALL TOWARDS
WEST
- NM-179-B-18 FROM NORTHEAST CORNER OF SITE TOWARDS WEST, NORTH
ROW OF ROOMS AT RIGHT, INTERIOR PASSAGEWAY AT LEFT
- NM-179-B-19 VIEW FROM NORTHWEST CORNER OF SITE TOWARDS EAST,
NORTH WALL BOTTOM CENTER TO TOP CENTER
- NM-179-B-20 INTERIOR WALL DETAIL, VIEW TOWARDS EAST
- NM-179-B-21 VIEW FROM NORTHWEST CORNER OF SITE TOWARDS
SOUTHEAST, INTERIOR PASSAGEWAY RUNS FROM LOWER
RIGHT TO UPPER LEFT
- NM-179-B-22 VIEW FROM NORTHWEST CORNER OF SITE TOWARDS SOUTH,
REMAINS OF WEST WALL AT RIGHT
- NM-179-B-23 KIVA, VIEW TOWARDS NORTHWEST
- NM-179-B-24 KIVA, VIEW TOWARDS NORTH
- NM-179-B-25 DETAIL OF KIVA WALL, VIEW TOWARDS NORTH