

# HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

ZUNI DAM  
(Black Rock Dam)  
Across Zuni River  
Black Rock vicinity  
McKinley County  
New Mexico

HAER NM-7

## INDEX TO BLACK AND WHITE PHOTOGRAPHS

Clayton B. Fraser, photographer, April 1995

- |         |   |
|---------|---|
| NM-7-1  | Overall view of Dam. View to east.  |
| NM-7-2  | Overall view of Dam, with spillway at right. View to northeast.                                 |
| NM-7-3  | Overall view of Dam along crest. View to north.   |
| NM-7-4  | Overall view of downstream face of Dam. View to southeast.                                      |
| NM-7-5  | Downstream face of rockfill section of Dam. View to southeast.                                  |
| NM-7-6  | Downstream face of rockfill section of Dam. View to northeast.                                  |
| NM-7-7  | Detail of downstream face of rockfill section of dam. View to north.                            |
| NM-7-8  | Detail of stepped stone courses on downstream face of rockfill section of Dam. View to east.    |
| NM-7-9  | Dam crest at north abutment, with inlet tower and bridge at left background. View to southeast. |
| NM-7-10 | Dam crest near south spillway. View to north.   |
| NM-7-11 | Detail of upstream face of Dam's raised north section. View to northwest.                       |
| NM-7-12 | Detail of rip rap placed on lakeshore north of Dam. View to north.                              |
| NM-7-13 | Detail of dedication stone on north wall of spillway, view to north.                            |

ZUNI DAM  
HAER NM-7  
INDEX TO PHOTOGRAPHS

- NM-7-14 Overall view of spillway at south end of dam. View to north.
- NM-7-15 Overall view of spillway at south end of Dam. View to east.
- NM-7-16 Mouth of spillway at south end of Dam, showing footbridge and tainter gate piers. View to north.
- NM-7-17 Detail of footbridge and tainter gate piers at mouth of spillway, from dam crest. View to southwest.
- NM-7-18 Detail of footbridge and tainter gate piers at mouth of spillway, from spillway floor. View to southeast.
- NM-7-19 Wrecked tainter gates near north abutment of dam. View to east.
- NM-7-20 Footbridge to inlet tower. View to east.
- NM-7-21 Footbridge to inlet tower. View to southeast.
- NM-7-22 Top of inlet tower. View to southeast.
- NM-7-23 Detail of typical vertical on footbridge to inlet tower. View to southeast.
- NM-7-24 Detail of bearing shoe on footbridge to inlet tower. View to northwest.
- NM-7-25 Outlet pipe downstream from Dam. View to east.
- NM-7-26 Outlet pipe and irrigation ditch downstream from dam. View to west.
- NM-7-27 Photocopy of photograph, photographer unknown, ca. 1906 (original print located at National Museum of the American Indian, New York New York). Rockfill section of Zuni Dam under construction.
- NM-7-28 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, September 1909 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). Ruin of spillway in aftermath of September 1909 flood.

ZUNI DAM  
HAER NM-7  
INDEX TO PHOTOGRAPHS

- NM-7-29 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, September 1909 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). Ruins of Spillway in aftermath of September 1909 flood, showing cracked wall at left.
- NM-7-30 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, September 1909 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). Man standing in front of wrecked spillway after September 1909 flood.
- NM-7-31 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, September 1909 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). Wrecked spillway at south end of Dam After September 1909 flood.
- NM-7-32 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, September 1909 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). Detail of wrecked spillway at south end of Dam after September 1909 Flood.
- NM-7-33 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, Photographer, 1911 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Drilling by hand and power - Zuni."
- NM-7-34 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1912 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). " The trench and cut off wall."
- NM-7-35 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1912 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Trench and wall - Zuni."

ZUNI DAM  
HAER NM-7  
INDEX TO PHOTOGRAPHS

- NM-7-36 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "The Dam, looking south."
- NM-7-37 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Blanketing slope. north end of Dam."
- NM-7-38 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). Placing concrete in trench for cutoff wall under spillway.
- NM-7-39 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). Reconstruction of spillway, with north end of Dam in background.
- NM-7-40 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). Reconstruction of spillway, with north end of Dam at left.
- NM-7-41 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). Grading floor of spillway, with top of cutoff wall visible in foreground.
- NM-7-42 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Placing concrete on floor of spillway with haynes concrete mixer."

ZUNI DAM  
HAER NM-7  
INDEX TO PHOTOGRAPHS

- NM-7-43 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Spillway from the east."
- NM-7-44 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "The finished cutoff wall, showing the cross walls."
- NM-7-45 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "South spillway wall. Top cutoff wall behind. Camp in distance."
- NM-7-46 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Outlet tower and footbridge."
- NM-7-47 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Lower side [of] Dam, outlet tunnel and lined section [of] canal."
- NM-7-48 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "The outlet tunnel."
- NM-7-49 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Interior of tunnel looking in."
- NM-7-50 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Hand excavating point of rock."

ZUNI DAM  
HAER NM-7  
INDEX TO PHOTOGRAPHS

- NM-7-51 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Excavation for the 'lined section' [of main canal]."
- NM-7-52 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Excavating the 'lined section' [of main canal]."
- NM-7-53 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Workers at canal."
- NM-7-54 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Excavating thin layer of rock."
- NM-7-55 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Placing the lining, lined section."
- NM-7-56 Photocopy of photograph, H.F. Robinson, Superintendent of Irrigation, U.S. Indian Service, photographer, 1913 (original print located at Bureau of Indian Affairs, Albuquerque, New Mexico). "Twin flume placed in main canal, Zuni."