

## HISTORIC AMERICAN BUILDINGS SURVEY

### INDEX TO PHOTOGRAPHS

CROWNPOINT HOSPITAL  
(CR-37)  
Lombardy Street  
Crownpoint  
McKinley County  
New Mexico

HABS NM-195

### INDEX TO BLACK AND WHITE PHOTOGRAPHS

Jerry Rabinowitz, photographer, October 2000

- |          |   |
|----------|---|
| NM-195-1 | General view illustrating environment and landscape. Looking southwest, east wing (left), north wing (center), west wing (right)                                    |
| NM-195-2 | Perspective view, main entrance, north and west wings with scale, looking southeast   |
| NM-195-3 | Perspective view, main entrance, north and west wings without scale, looking southeast  |
| NM-195-4 | West end of west wing, original ambulance entrance, with scale, looking east. Note original construction and cinder block outpatient addition                       |
| NM-195-5 | Perspective view, west wing, original construction and outpatient addition showing contrast in materials and fire damage on west and south walls, looking northeast |

CROWNPOINT HOSPITAL  
HABS NM-195  
INDEX TO PHOTOGRAPHS  
Page 2

- NM-195-6 West wing, south side, partial original construction (background) and outpatient addition (foreground), showing fire damage, looking north
- NM-195-7 Patio, south end of south wing with scale, facing north
- NM-195-8 Patio, south end of south wing, showing low stone walls, facing northwest
- NM-195-9 Perspective view, south and east wings, facing northwest
- NM-195-10 East end of east wing, detail of exterior hopper window treatment, stone work and canale, looking west
- NM-195-11 Perspective view, east and north wings, looking southwest
- NM-195-12 Delivery (surgery) room window from outside, north end of north wing, looking south
- NM-195-13 Interior detail, main floor, near hospital center, looking north toward delivery (surgery) room, west wing and nurses station (left), east wing (right)
- NM-195-14 Interior detail, west wing from nurses station showing fire damage, looking west
- NM-195-15 Interior detail, nurses station, facing east toward 'service window', to left radiator and main entryway (see HABS NM-195-16)
- NM-195-16 Interior detail, main entryway doors, built in bench seating to left, radiator ahead and right and nurses station 'service window' to right, facing north (see HABS NM-195-15)
- NM-195-17 Interior detail, north wing, delivery (surgery) room window and glass closet, facing northeast
- NM-195-18 Interior detail, delivery (surgery) room, facing south, main entry doors and side doors to storage (left) and ward room (right), window to rear