

Historic American Buildings Survey
Index To Photographs

HABS
OHIO
18-CLEV,
14-

Addendum To:
Society National Bank Building
127-145 Public Square
Cleveland
Cuyahoga County
Ohio

HABS No. OH-2128

Photographer: 1-101/103-115 - Jennie Jones
Photographer: 102/116-138 - Rick Sherlock

January-March, 1989

Ten photographs were previously transmitted to the Library of Congress

Exterior

- OH-2128-11 View north: west side & south front 1/23/89
OH-2128-12 View northwest: south front & east side 1/23/89
OH-2128-13 View west: east side 1/23/89
OH-2128-14 View southwest: east side & north rear 3/22/89
OH-2128-15 Detail: view south, entrance on east side 3/22/89
OH-2128-16 Detail: view southwest: entrance on east side 3/22/89
OH-2128-17 Detail: view southwest: lower window arch
east side 3/22/89
OH-2128-18 Detail: view southwest: northeast corner/w fire escape 3/22/89
OH-2128-19 Detail: view west: northeast turret/fire escape 3/22/89
OH-2128-20 Detail: view southwest: fire escape/turret 3/22/89
OH-2128-21 Detail: view west: fire escape/turret 3/22/89
OH-2128-22 Detail; window treatment 2/3/4th floors 3/22/89
OH-2128-23 Detail: window treatment: 6,7,8,9th floors 3/22/89
OH-2128-24 View northeast: atrium roof/elevator room machinery 1/31/89
OH-2128-25 Detail: southwest corner; replica Brush arc lamp 1/23/89
OH-2128-26 Detail: head, south front, west end 1/23/89
OH-2128-27 Detail: head, south front, west end 1/23/89
OH-2128-28 Detail: head, south front, east end 1/23/89
OH-2128-29 Detail: head, south front, east end 1/23/89

Interior: Upper floors/Atrium

- OH-2128-30 View southeast: attic/ top of atrium 1/31/89

OH-2128-31 View southwest: 9th floor elevator area 3/23/89
OH-2128-32 View northwest: 9th floor atrium 3/23/89
OH-2128-33 View northwest: 8th floor office space 3/23/89
OH-2128-34 View west: 7th floor: Detail stairs 2/23/89
OH-2128-35 View southeast: 7th floor typical office space 3/23/89
OH-2128-36 View southeast: 6th floor: atrium 2/23/89
OH-2128-37 View northwest: 4th floor: typical office area 2/23/89
OH-2128-38 View northeast: 4th floor: office dining area 2/23/89
OH-2128-39 View west: 4th floor: typical office area 3/23/89
OH-2128-40 View southeast: 2nd floor: atrium area 1/31/89
OH-2128-41 View north: 2nd floor: typical office area 1/31/89
OH-2128-42 View south: southeast stair well 1/31/89

Interior: Oak Board Room/Mezzanine

OH-2128-43 View north: mezzanine elevator 1/19/89
OH-2128-44 View Northeast: reception room, east wall 4/5/89
OH-2128-45 View west: reception room/ w elevator lobby and doorway to "secret" stairs 1/19/89
OH-2128-46 View south: south wall/window in reception room:"secret" door open 1/19/89
OH-2128-47 View south: reception room: south wall/window 2/01/89
OH-2128-48 Detail: hanging fixture in reception room 2/01/89
OH-2128-49 View northeast: "secret" stair from ground floor 3/30/89
OH-2128-50 View south: "secret" stair showing small safe 3/30/89

OH-2128-51 View south: entrance from board room into reception room 4/5/89
OH-2128-52 Detail: view west: door in board room connecting into the reception area 2/01/89

OH-2128-53 View west: west and north wall, view into reception area 1/19/89
OH-2128-54 View south: south wall/window treatment in board room 2/01/89
OH-2128-55 View southeast: Detail window treatment 1/19/89
OH-2128-56 Detail: overhanging lamp in oak board room 1/04/89
OH-2128-57 View North: north wall/fireplace wall (east) 1/19/89
OH-2128-58 View northeast: fireplace on east wall 1/19/89
OH-2128-59 View northeast: fireplace on east wall 1/04/89
OH-2128-60 Detail: view north: corner treatment 1/04/89
OH-2128-61 Detail: columns on south side of fireplace 1/04/89
OH-2128-62 Detail: column on north side of fireplace 1/04/89
OH-2128-63 Detail: view south: corner treatment 1/04/89
OH-2128-64 Detail: view northwest: mural and wood treatment 1/04/89

OH-2128-65 View southeast: Detail: wood carving 2/01/89
OH-2128-66 Detail: view north: wood treatment 1/19/89
OH-2128-67 Detail: carved oak, south side of fireplace 1/04/89

Interior: Ground floor/Elevator lobby

OH-2128-68 View west: west and north wall: southeast elevator lobby 2/10/89
OH-2128-69 View east: south wall: southeast elevator lobby 3/30/89
OH-2128-70 View northeast: north wall, east wall, south wall southeast elevator lobby 3/30/89

Interior: Ground floor/Back offices

OH-2128-71 View north: office space 4/5/89
OH-2128-72 View south: office space 4/5/89
OH-2128-73 View southwest: office space 4/5/89
OH-2128-74 View northwest: office space 4/5/89

Interior: Ground floor/New Accounts Rooms

OH-2128-75 View northeast: New Accounts Room: facing north wall 3/30/89
OH-2128-76 View southwest: New Accounts Room 3/30/89
OH-2128-77 View northeast: New Accounts Room 3/30/89

Interior: Ground floor/Banking Lobby


OH-2128-78 View southeast: hallway 2/01/89
OH-2128-79 View southeast: northeast wall/ south east wall 1/31/89
OH-2128-80 View east: northeast wall and entrance area 4/5/89
OH-2128-81 View west: facing southwest wall 2/10/89
OH-2128-82 View southwest: facing southwest wall 4/5/89
OH-2128-83 View south: facing south west wall 4/5/89
OH-2128-84 View north: northeast wall/ window treatment 4/5/89
OH-2128-85 View northeast 4/5/89
OH-2128-86 View northeast: facing northeast entrance /wall 2/22/89
OH-2128-87 View northeast: facing northeast entrance wall 2/22/89
OH-2128-88 View southeast: facing southeast corner 1/31/89
OH-2128-89 View northwest 4/05/89
OH-2128-90 View west: stairs to safety deposit area 2/10/89
OH-2128-91 View south: column/writing area 2/10/89
OH-2128-92 View east: Detail of writing area 2/01/89

OH-2128-93 Detail: lamp fixture: southeast corner of lobby 2/01/89
OH-2128-94 Detail: detail of same lamp fixture 2/01/89
OH-2128-95 Detail: Column: from northeast corner: center column 2/01/89
OH-2128-96 Detail: Capital of column 2/01/89
OH-2128-97 Detail: capital of column/ ceiling detail 2/10/89
OH-2128-98 Detail: northwest wall section 2/01/89
OH-2128-99 Detail: mural southeast corner 2/22/89
OH-2128-100 Detail: mural northwest corner 2/22/89
OH-2128-101 Detail: Mural southwest corner 2/22/89
OH-2128-102 Detail: mural northeast corner 5/1/89
OH-2128-103 Detail: stained glass ceiling: southwest corner/
right of New Accounts Room 2/01/89
OH-2128-104 Detail: stained glass ceiling: southwest corner/
right of New Accounts 2/01/89


Interior: Basement

OH-2128-105 View west: water heater: general basement scene 1/04/89
OH-2128-106 View north: steam heating system 1/04/89
OH-2128-107 View east: electrical system 1/03/89
OH-2128-108 View north: support pads 1/04/89
OH-2128-109 Detail: view southeast: support pads 1/03/89
OH-2128-110 Detail: view south: brick/arch work 1/04/89
OH-2128-111 View east: entrance to safety deposit vaults 1/03/89
OH-2128-112 View east: vault 1/07/89
OH-2128-113 Detail: vault door 1/07/89
OH-2128-114 Detail: vault mechanism 1/07/89
OH-2128-115 View north: safety deposit customer security rooms 1/03/89


EXTERIOR ROOF VIEWS




TENTH FLOOR (ATTIC)




NINTH FLOOR




EIGHTH FLOOR




SEVENTH FLOOR




SIXTH FLOOR




FOURTH FLOOR




SECOND FLOOR



MEZZANINE



GROUND FLOOR



BASEMENT

