

156 Wilson Avenue (House)
Columbus
Franklin County
Ohio

HABS No. OH-2290

HABS
OHIO,
25-COLB,
41-

PHOTOGRAPHS


WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PA 19106


HABS
OHIO,
25-COLE,
41-

ARCHITECTURAL DATA FORM


STATE OHIO	COUNTY FRANKLIN	TOWN OR VICINITY COLUMBUS
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) 156 Wilson Avenue (house)		HABS NO. OH-2290
SECONDARY OR COMMON NAMES OF STRUCTURE N/A		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 156 Wilson Avenue, Columbus Ohio 43205		
DATE OF CONSTRUCTION (INCLUDE SOURCE) ca. 1890-1900 Based on an incomplete set of Baist Atlases and Sandborn Insurance maps.	ARCHITECT(S) (INCLUDE SOURCE) Unknown	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The building contributes to a historic district of intact residences constructed between 1890 and 1910. It's features include Queen Ann details in window and dormer treatments.		
STYLE (IF APPROPRIATE) Queen Ann		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Brick with wood framing and a wood frame addition.		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) See attached floor plans		
EXTERIOR FEATURES OF NOTE The building has two projecting pedimented gables. Wooden panels with sunburst designs decorate the eaves of the building and pediment. Ornamental metal cresting and a corbeled chimney are also present. The porch has a hipped roof.		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) The building has a highly irregular and asymmetrical floor plan. It has simple panel doors and moulding. Many of the fireplace mantles have been removed. The building has plaster pointed arched openings between several of the rooms.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES The rear frame addition dates from about 1910. The building was divided into apartments in the 1940's. At that time the front staircase was enclosed and some doorways covered over.		
PRESENT CONDITION AND USE Vacant, fair		
OTHER INFORMATION AS APPROPRIATE The building has been declared a nuisance by the Columbus Nuisance abatement board. The building is slated for demolitio No alternatives to the demolition of the building can be found.		
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Building is a part of the Near East Side National Register District.		
COMPILER, AFFILIATION Kevin Wheeler	DATE 7-26-88	



Sanborn Insurance Map-1922



First Floor Plan



Second Floor Plan