

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

SCHEETZ FARM, HOUSE
7161 Camp Hill Road
Fort Washington vicinity
Montgomery County
Pennsylvania

HABS PA-6666-A

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Nancy Holst, Mary Alfson, Laura Black, Sarah Goode, photographers, October 2000

- | | |
|-------------|--|
| PA-6666-A-1 | Northwest gable and southwest elevation, looking north. Note ridgeline off-center from northwest gable. |
| PA-6666-A-2 | Southeast gable. Looking northwest. Note extension to rear of two-story block. |
| PA-6666-A-3 | Southeast and northeast elevation of Federal addition and rear kitchen ell. Looking southwest. |
| PA-6666-A-4 | Northwest elevation of elevation of kitchen ell; northeast elevation of main house and one-story additions. Looking south. |
| PA-6666-A-5 | Detail of door in northwest elevation of kitchen ell. Note masonry seam to right of door, showing rear wall of Federal addition. |
| PA-6666-A-6 | Detail of masonry seam in southwest elevation, between original house and Federal addition; also simulated ashlar finish of Federal addition underneath current stucco. Left window unaltered from original house. |
| PA-6666-A-7 | Side passage of Federal addition, looking southwest towards front of house. |
| PA-6666-A-8 | Side passage of Federal addition, looking northeast towards rear of house; rear kitchen visible through doorway. |

SCHEETZ FARM, HOUSE
HABS PA-6666-A
INDEX TO PHOTOGRAPHS
(Page 2)


- PA-6666-A-9 Front first-floor room of Federal addition looking northwest through passage.
- PA-6666-A-10 Rear first-floor room of Federal addition, front room to left and stair passage to right.
- PA-6666-A-11 Southeast room of northwest wing (now accessed only from Federal addition, to left); looking towards front of house; window frame unaltered from original house.
- PA-6666-A-12 Second-floor passage of Federal addition, looking towards bathroom at front of house.
- PA-6666-A-13 Northeast wall of rear kitchen ell.
- PA-6666-A-14 Northeast wall of rear kitchen chamber.
- PA-6666-A-15 Central first-floor room of northwest wing, looking through entry to northwestern room. note crack in ceiling showing location of summer beam.
- PA-6666-A-16 Detail of summer beam in southeast wall of stairwell, northwest wing of house.
- PA-6666-A-17 Central room of northwest wing, looking northeast towards rear wall with built-in cupboard.
- PA-6666-A-18 Northwestern room of northwest wing looking northeast towards rear wall showing entrances to one story additions.
- PA-6666-A-19 Northwester upstairs room of northwest wing looking southeast through stair landing and hallway to southeast room. note far floorboard with smoke damage between historic joists; modern joists in stair landing.
- PA-6666-A-20 Southeast upstairs room of northwest wing showing southeast masonry wall shared with Federal addition. note angled cracks showing original 1 1/2 story gable.
- PA-6666-A-21 Half-cellar underneath original house showing fireplace relieving arch at northwest end; enclosed "cheese" room to right
- PA-6666-A-22 "Cheese" room in half-cellar showing stone trough, later fireplace supports, stairs inserted in original relieving arch.

SCHEETZ FARM, HOUSE
HABS PA-6666-A
INDEX TO PHOTOGRAPHS
(Page 3)

PA-6666-A-23



Attic over northwest wing showing fishmouth collar beams; note roman numerals and cocked gable.

SCHEETZ FARM, HOUSE
 HABS No. PA-6666-A
 Key to Photographs
 (Page 4)



SECOND FLOOR PLAN



- OVERHEAD
- - - MISSING
- ▨ BRICK
- ▩ CONCRETE
- ▧ STONE



SCHEETZ FARM, HOUSE
 HABS No. PA-6666-A
 Key to Photographs
 (Page 6)

CELLAR PLAN

- OVERHEAD
- - - MISSING
- ▨ BRICK
- ▩ CONCRETE
- ▧ STONE



Prepared by N. Holst, C.H.R.S., Inc.

