

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
SC,
10-CHAR,
103A-

Thomas Heyward, Jr. Kitchen Building
87 Church Street
Charleston
Charleston County
South Carolina

HABS No. SC-64 A

This recording is one of those selected for the 1977-79 South Carolina project made possible by grants from the National Endowment for the Arts. Charles N. Bayless, AIA, was the photographer.

PHOTO DATE: OCTOBER 1977

SC-64 A-1 GENERAL VIEW

SC-64 A-2 EAST ROOM, WEST WALL, SHOWING FIREPLACE AND OVEN.
STAIRWAY LEADS TO SLAVE QUARTERS

SC-64 A-3 WEST ROOM (LAUNDRY ROOM), EAST WALL, SHOWING FIREPLACE.
KITCHEN IN BACKGROUND

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
SC
10-0418
103A-

**ADDENDUM TO
THOMAS HEYWARD, JR., HOUSE, KITCHEN**
87 Church Street
Charleston
Charleston County
South Carolina

HABS No. SC-64-A
(page 2)

Photographs HABS No. SC-64-A-1 to HABS No. SC-64-A-3 were transmitted previously to the Library of Congress.

This recording project of the Carolina Low Country, by photographer Charles N. Bayless, took place between 1970 and 1988. Bayless's work was made possible by several grants from the National Endowment for the Arts during that interval.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Charles N. Bayless, Photographer, n.d.

- SC-64-A-4 SOUTH SIDE, VIEW OF THE WEST END
- SC-64-A-5 SOUTH SIDE, VIEW OF THE EAST END
- SC-64-A-6 SOUTH SIDE, VIEW OF WELL UNDER THE EAST END DOOR
- SC-64-A-7 WEST SIDE
- SC-64-A-8 NORTH SIDE
- SC-64-A-9 EAST SIDE, SECOND FLOOR
- SC-64-A-10 INTERIOR VIEW, FIRST FLOOR EAST ROOM, EAST WALL
- SC-64-A-11 INTERIOR VIEW, FIRST FLOOR EAST ROOM, NORTH AND EAST WALLS
- SC-64-A-12 INTERIOR VIEW, SECOND FLOOR EAST ROOM, NORTH WALL
- SC-64-A-13 INTERIOR VIEW, SECOND FLOOR EAST ROOM, EAST WALL
- SC-64-A-14 INTERIOR VIEW, SECOND FLOOR EAST ROOM, LOOKING SOUTHWEST TO STAIRS
- SC-64-A-15 INTERIOR VIEW, SECOND FLOOR WEST ROOM, NORTH WALL
- SC-64-A-16 INTERIOR VIEW, SECOND FLOOR WEST ROOM, WEST WALL

THOMAS HEYWARD, JR., HOUSE, KITCHEN
HABS No. SC-64-A
INDEX TO PHOTOGRAPHS
(page 3)

- SC-64-A-17 INTERIOR VIEW, SECOND FLOOR WEST ROOM, LOOKING SOUTHEAST INTO STAIRS
- SC-64-A-18 INTERIOR VIEW, THIRD FLOOR EAST ROOM, LOOKING SOUTHWEST INTO DORMER CHEEK
- SC-64-A-19 INTERIOR VIEW, THIRD FLOOR LOOKING SOUTHWEST TO STAIRS FROM THE EAST ROOM
- SC-64-A-20 INTERIOR VIEW, THIRD FLOOR WEST ROOM, LOOKING SOUTHEAST TO STAIRS
- SC-64-A-21 INTERIOR VIEW, BASEMENT, SOUTH WALL SHOWING ARCH IN WALL WHERE THE WALL WAS BUILT OVER THE WELL
- SC-64-A-22 INTERIOR VIEW, BASEMENT, SOUTH WALL SHOWING BRICKED-UP STEPS TO EXTERIOR
- SC-64-A-23 INTERIOR VIEW, BASEMENT, EAST WALL SHOWING BRICKED-UP ORIGINAL DOOR
- SC-64-A-24 INTERIOR VIEW, BASEMENT, SHOWING REPAIRED EAST SIDE OF CHIMNEY FOUNDATION
- SC-64-A-25 INTERIOR VIEW, BASEMENT, SHOWING REPAIRED WEST SIDE OF CHIMNEY FOUNDATION