



HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

The Church of the Holy Cross  
State Route 261  
Stateburg  
Sumter County  
South Carolina

HABS No. SC-13-14

Addendum to  
Episcopal Church of the Holy Cross  
State Highway 261  
Statesburg  
Sumter County  
South Carolina

Photos SC-13-14-1 through 6 were transmitted to the Library of Congress in 1926. Photos SC-13-14-7 through 9 were transmitted in 1960.

- SC-13-14-10 Photocopy of an engraving of a stained glass window design by Johann Friedrich Overbeck (1789-1869) on which two of the chancel windows in the Church of the Holy Cross are thought to have been based. This copy is of a photocopy obtained from the Treasury of Notre Dame de Paris, Paris, France, by the late Mrs. Walter C. White of Stateburg, South Carolina. Mrs. White's photocopy is in the possession of Mrs. Richard K. Anderson of the Borough House at Stateburg.
- SC-13-14-11 Photocopy of photograph (original color slide made in 1974 by Henry D. Boykin, II, A.I.A., of Camden, South Carolina, and kept in his possession)  
OBLIQUE VIEW, SECTION OF SOUTH WALL OF NAVE SHOWING INTERNAL CONSTRUCTION OF ORIGINAL BRICK BUTTRESS AND RAMMED EARTH WALL.
- SC-13-14-12 Photocopy of photograph (original color slide made in 1974 by Henry D. Boykin, II, A.I.A., of Camden, South Carolina, and kept in his possession)  
FULL SECTIONAL VIEW OF SOUTH WALL OF NAVE SHOWING TYPICAL INTERNAL CONSTRUCTION AND MATERIALS OF CHURCH WALLS. BRICK BUTTRESS WITH CREPE COVERING ON LEFT; RAMMED EARTH WALL CORE IN CENTER (ADZE MARKS ARE FROM 1974 REPAIR PROCESS); INTERIOR LATH, PLASTER, AND CORNICE ON RIGHT. NOTE REMAINS OF EMBEDDED WOODEN BRACES (NEAR BUTTRESS) USED TO HOLD WALL FORMS DURING ORIGINAL CONSTRUCTION OF WALLS.
- SC-13-14-13 Photocopy of color photograph (Photographer unknown, 1974)  
INTERIOR OF SACRISTY LOOKING NORTHEAST, SHOWING FURRING AND METAL LATH PUT IN DURING 1974 RESTORATION

The Church Of the Holy Cross  
HABS SC-13-14 (page 2)  
INDEX TO PHOTOGRAPHS 3

- SC-13-14-14 Photocopy of color photograph (Photographer unknown, 1974)  
SACRISTY CEILING CONSTRUCTION, LOOKING EAST
- SC-13-14-15 Photocopy of color photograph (Photographer unknown, 1974)  
SACRISTY ATTIC, LOOKING SOUTHWEST. NOTE RAMMED EARTH WALL  
(NORTH WALL OF CHANCEL) AT LEFT; HOLES WERE LEFT BY WOODEN  
BRACES USED TO HOLD WALL FORMS DURING CONSTRUCTION
- Jack E. Boucher, Photographer, May 1985 (Photos SC-13-14-16 through 91)
- SC-13-14-16 GENERAL VIEW THROUGH GATES FROM SOUTHWEST
- SC-13-14-17 GENERAL VIEW FROM SOUTHWEST
- SC-13-14-18 DETAIL OF GATES TO THE SOUTHWEST OF THE CHURCH STRUCTURE; ACTUAL  
VIEW OF GATES IS FROM SOUTHWEST (GATES TO NORTHWEST ARE SIMILAR)
- SC-13-14-19 DETAIL VIEW OF WEST FRONT AND WEST END OF SOUTH SIDE OF CHURCH  
FROM SOUTHWEST; PARISH HOUSE VISIBLE IN BACKGROUND
- SC-13-14-20 GENERAL VIEW OF CHURCH FROM WEST SOUTHWEST
- SC-13-14-21 WEST (FRONT) FACADE
- SC-13-14-22 WEST (FRONT) FACADE
- SC-13-14-23 GENERAL VIEW OF CHURCH FROM NORTHWEST
- SC-13-14-24 GENERAL VIEW OF CHURCH FROM NORTHWEST
- SC-13-14-25 TELEPHOTO VIEW OF ESCUTCHEON WITH DATE, WEST (FRONT) FACADE
- SC-13-14-26 DETAIL OF ENTRANCE, NORTH SIDE OF WEST (FRONT) FACADE
- SC-13-14-27 SOUTH FACADE
- SC-13-14-28 DETAIL OF BUTTRESSES AND FENESTRATION, CORNER OF WEST (FRONT)  
AND SOUTH FACADES
- SC-13-14-29 DETAIL OF PORCH ENTRY TOWARD WEST END OF SOUTH FACADE, FROM  
SOUTHWEST
- SC-13-14-30 DETAIL OF PORCH ENTRY, FROM SOUTH
- SC-13-14-31 DETAIL OF SOUTH FACADE FROM SOUTHWEST, SHOWING TYPICAL  
BUTTRESSES, FENESTRATION, AND CUTTERS; FRAMED AREA ON WALL IS  
EXHIBIT OF UNDERLYING LAYERS OF CRÉPÉ WALL COATINGS AND RAMMED  
EARTH CORE OF WALL

The Church of the Holy Cross  
HABS No. SC-13-14 (page 3)  
INDEX TO PHOTOGRAPHS

- SC-13-14-32 DETAIL OF FRAMED EXHIBIT IN SOUTH FACADE, SHOWING UNDERLYING WALL COATINGS AND RAMMED EARTH CORE OF WALL
- SC-13-14-33 EAST (REAR) FACADE
- SC-13-14-34 NORTH FACADE
- SC-13-14-35 DETAIL OF SACRISTY ENTRANCE, EAST OF NORTH TRANSEPT ON NORTH FACADE
- SC-13-14-36 DETAIL OF GRAVE MARKER ABUTTING FOUNDATION AT NORTHEAST CORNER OF NORTH TRANSEPT
- SC-13-14-37 VIEW OF PARISH HOUSE FROM SOUTHEAST
- SC-13-14-38 VIEW OF PARISH HOUSE FROM SOUTHWEST
- SC-13-14-39 VIEW OF PARISH HOUSE FROM NORTHWEST
- SC-13-14-40 GENERAL VIEW FROM SOUTHWEST OF FRIERSON AND VAUGHAN CEMETERY PLOT SURROUNDED BY ORNATE CAST IRON FENCE, TO EAST NORTHEAST OF CHURCH HABS SC, 43 - STATBU.V, 1A-1
- SC-13-14-41 DETAIL VIEW OF CAST IRON GATEWAY AND FENCE OF FRIERSON AND VAUGHAN CEMETERY PLOT, FROM SOUTHWEST HABS SC, 43 - STATBU.V, 1A-2
- SC-13-14-42 DETAIL OF CAST IRON GATEWAY TO FRIERSON AND VAUGHAN PLOT HABS SC, 43 - STATBU.V, 1A-3
- SC-13-14-43 DETAIL OF TOP OF CAST IRON GATEWAY TO FRIERSON AND VAUGHAN CEMETERY PLOT, SHOWING YEAR OF CONSTRUCTION (1860) AND DETAILS OF CASTINGS HABS SC, 43 - STATBU.V, 1A-4
- SC-13-14-44 VIEW OF NORTHEAST CORNER OF CHURCHYARD FROM NORTH SIDE OF FRIERSON AND VAUGHAN CEMETERY PLOT HABS SC, 43 - STATBU.V, 1A-5
- SC-13-14-45 DETAIL VIEW FROM NORTHEAST OF CAST IRON GATEWAY AND FENCE SURROUNDING CONVERSE AND FRIERSON CEMETERY PLOT, TO SOUTHEAST OF CHURCH HABS SC, 43 - STATBU.V, 1A-6
- SC-13-14-46 SILHOUETTE OF CAST IRON GATEWAY TO CONVERSE AND FRIERSON CEMETERY PLOT, FROM SOUTH HABS SC, 43 - STATBU.V, 1A-7
- SC-13-14-47 DETAIL FROM NORTHWEST OF TOMBS OF JOEL ROBERTS POINSETT AND WIFE, TO SOUTHEAST OF CHURCH HABS SC, 43 - STATBU.V, 1A-8

- SC-13-14-48    DETAIL OF INTERIOR CORNICE AT CORNER OF SOUTH WALL OF NAVE AND WEST WALL OF SOUTH TRANSEPT, FROM NORTH
- SC-13-14-49    DETAIL OF INTERIOR CORNICE AT CORNER OF SOUTH WALL OF NAVE AND WEST WALL OF SOUTH TRANSEPT, FROM NORTHWEST
- SC-13-14-50    DETAIL OF WOODEN ROOF TRUSSES AT CROSSING OF TRANSEPTS AND NAVE
- SC-13-14-51    DETAIL OF WOODEN ROOF TRUSSES AT CROSSING OF TRANSEPTS AND NAVE
- SC-13-14-52    VIEW OF WOODEN ROOF TRUSSES IN SOUTH TRANSEPT AND CROSSING, FROM NORTH
- SC-13-14-53    DETAIL OF PENDANT AT CROSSING OF ROOF TRUSSES AT CROSSING OF TRANSEPTS AND NAVE
- SC-13-14-54    GENERAL VIEW FROM NARTHEX EAST TOWARD CHANCEL
- SC-13-14-55    GENERAL VIEW FROM NAVE EAST TOWARD CHANCEL
- SC-13-14-56    GENERAL VIEW FROM CROSSING OF NAVE AND TRANSEPTS EAST INTO CHANCEL, SHOWING CHANCEL ARCH, VAULTING, WINDOWS, ALTAR, AND OTHER FEATURES
- SC-13-14-57    DETAIL OF EAST END OF CHANCEL SHOWING BISHOP'S CHAIR, ALTAR, AND STAINED CLASS WINDOWS; NOTE MINTON TILE MEDALLIONS ON FLOOR
- SC-13-14-58    DETAIL OF EAST END OF CHANCEL SHOWING BISHOP'S CHAIR, ALTAR, AND STAINED CLASS WINDOWS
- SC-13-14-59    DETAIL OF ALTAR FROM NORTHWEST
- SC-13-14-60    DETAIL OF BISHOP'S CHAIR
- SC-13-14-61    DETAIL OF CREDENCE SHELF IN NORTH WALL OF CHANCEL
- SC-13-14-62    DETAIL OF CREDENCE SHELF IN NORTH WALL OF CHANCEL
- SC-13-14-63    DETAIL OF PISCINA AND SEDILIA ON SOUTH WALL OF CHANCEL (WITH COMMUNION RAIL), FROM NORTHWEST
- SC-13-14-64    DETAIL OF PISCINA IN CHANCEL, FROM NORTH
- SC-13-14-65    DETAIL, TOP OF SEDILIA BAY, FROM NORTH
- SC-13-14-66    DETAIL OF CHANCEL ARCADE, CONSOLES, VAULT RIBBING, AND BOSSES
- SC-13-14-67    DETAIL OF CHANCEL ARCADE, CONSOLES, VAULT RIBBING, AND BOSSES

The Church of the Holy Cross  
HABS No. SC-13-14 (page 5)  
INDEX TO PHOTOGRAPHS

- SC-13-14-68    DETAIL OF CHANCEL ARCADE, CONSOLES, VAULT RIBBING, BOSSES, AND  
                  CHANCEL WINDOW MOULDINGS IN NORTHEAST CORNER OF CHANCEL
- SC-13-14-69    GENERAL VIEW FROM SOUTHWEST SHOWING NORTH WALL OF CHANCEL,  
                  CHANCEL CEILING, AND WINDOWS
- SC-13-14-70    GENERAL VIEW OF CHANCEL CEILING FROM WEST
- SC-13-14-71    DETAIL OF COMMUNION RAIL FROM WEST
- SC-13-14-72    GENERAL VIEW OF SOUTH HALF OF COMMUNION RAIL INCLUDING GATE,  
                  FROM NORTHWEST
- SC-13-14-73    DETAIL OF MINTON TILE MEDALLION IN CHANCEL FLOOR
- SC-13-14-74    DETAIL OF TYPICAL PEW ENDS ON NORTH SIDE OF NAVE
- SC-13-14-75    DETAIL OF TYPICAL POPPY HEAD ON PEW END
- SC-13-14-76    DETAIL OF TYPICAL POPPY HEAD ON PEW END, WITH SCALE
- SC-13-14-77    VIEW IN NARTHEX FROM NORTH SHOWING BAPTISMAL FONT AND INTERIOR  
                  OF PORCH ENTRY
- SC-13-14-78    DETAIL OF BAPTISMAL FONT
- SC-13-14-79    GENERAL VIEW OF ARCADE ON WEST WALL OF PORCH INTERIOR
- SC-13-14-80    DETAIL OF ARCADE BAY AND ESCUTCHEON ON WEST WALL OF PORCH  
                  INTERIOR
- SC-13-14-81    ORIGINAL (1851) STAINED CLASS WINDOWS IN CHANCEL, AS SEEN FROM  
                  CHURCH INTERIOR
- SC-13-14-82    ORIGINAL (1851) STAINED CLASS WINDOWS IN NARTHEX, AS SEEN FROM  
                  CHURCH INTERIOR
- SC-13-14-83    TYPICAL ORIGINAL (1851) NAVE WINDOW, AS SEEN FROM CHURCH INTERIOR
- SC-13-14-84    GENERAL VIEW OF PIPE ORGAN (BUILT BY HENRY ERBEN IN 1851), FROM  
                  WEST SOUTHWEST
- SC-13-14-85    GENERAL VIEW OF PIPE ORGAN FROM NORTHWEST
- SC-13-14-86    DETAIL OF NORTH SIDE OF CHOIR BOX RAIL
- SC-13-14-87    DETAIL OF LITANY DESK, FROM NORTHWEST

The Church of the Holy Cross  
HABS No. SC-13-14 (page 6)  
INDEX TO PHOTOGRAPHS 7

- SC-13-14-88   DETAIL OF LECTERN, FROM NORTHWEST
- SC-13-14-89   WEST (FRONT) SIDE OF PULPIT
- SC-13-14-90   DETAIL OF PULPIT, FROM SOUTHWEST
- SC-13-14-91   DETAIL OF MEMORIAL PLAQUES ON EAST WALL OF NORTH TRANSEPT, NORTH  
OF PULPIT

HABS  
SC  
43-STATBU.V,  
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO  
CHURCH OF THE HOLY CROSS  
St. Rt. 261  
Stateburg  
Sumter County  
South Carolina

HABS No. SC-13-14  
(p. 7)

SC-13-14-1 through SC-13-14-91 were previously transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, May 1985

- SC-13-14-92 (CT) GENERAL VIEW FROM SOUTHWEST
- SC-13-14-93 (CT) DETAIL VIEW OF WEST FRONT AND WEST END OF SOUTH SIDE OF CHURCH FROM SOUTHWEST; PARISH HOUSE VISIBLE IN BACKGROUND
- SC-13-14-94 (CT) GENERAL VIEW OF CHURCH FROM WEST-SOUTHWEST
- SC-13-14-95 (CT) WEST (FRONT) FACADE
- SC-13-14-96 (CT) GENERAL VIEW OF CHURCH FROM NORTHWEST
- SC-13-14-97 (CT) ORIGINAL (1851) STAINED GLASS WINDOWS IN CHANCEL, AS SEEN FROM CHURCH INTERIOR
- SC-13-14-98 (CT) ORIGINAL (1851) STAINED GLASS WINDOWS IN NARTHEX, AS SEEN FROM CHURCH INTERIOR

## HISTORIC AMERICAN BUILDINGS SURVEY

### INDEX TO PHOTOGRAPHS

ADDENDUM TO:

HABS SC-13-14

CHURCH OF THE HOLY CROSS

State Route 261

Stateburg vicinity

Sumter County

South Carolina

Photographs HABS SC-13-14-1 through HABS SC-13-14-98 were previously transmitted to the Library of Congress.

### INDEX TO COLOR TRANSPARENCIES

Jack E. Boucher, photographer, May 1985

- |                   |  |
|-------------------|--|
| SC-13-14-99 (CT)  | General view through gates from southwest  |
| SC-13-14-100 (CT) | West front facade  |
| SC-13-14-101 (CT) | Detail of porch entry toward west end of south facade, from southwest  |
| SC-13-14-102 (CT) | Silhouette of iron gateway to converse and Frierson Cemetery plot, from south HABS SC, 43-STATBU. V, 1A-7                    |
| SC-13-14-103 (CT) | Detail of east end of chancel showing Bishop's chair, altar, and stained glass windows; note minton tile medallions on floor |