

HAER  
CAL  
14-BISH.V,  
2D-

HISTORIC AMERICAN ENGINEERING RECORD  
INDEX TO PHOTOGRAPHS

Bishop Creek Hydroelectric System, Control Station,  
Worker Cottage (Building 106)  
Bishop Creek  
Bishop Vicinity  
Inyo County  
California

HAER No. CA-145-1-D

Gregory L. O'Loughlin, photographer

April, 1997

- CA-145-1-D-1 EXTERIOR OVERVIEW SHOWING THE EAST SIDE OF BUILDING 106 IN FOREGROUND AT PHOTO CENTER LEFT AND BUILDING 103 IN BACKGROUND AT PHOTO CENTER RIGHT. EAST SIDE OF BUILDING 106 WAS THE ORIGINAL FRONT OF THE HOUSE. VIEW TO NORTHWEST FROM MAIN RESIDENTIAL STREET.
- CA-145-1-D-2 EXTERIOR OF NORTH AND WEST SIDES OF BUILDING 106. MODERN BLOCK RETAINING WALL AND CHAIN-LINK FENCE ENCLOSING BACKYARD AREA IN RIGHT FOREGROUND. FRONT ENTRY IS VISIBLE UNDER SHED-ROOF STRUCTURE AT EASTERN END OF NORTH WALL; BACK ENTRY IS AT LEFT-CENTER OF WEST WALL. VIEW TO SOUTHEAST.
- CA-145-1-D-3 EXTERIOR OF NORTH AND EAST SIDES OF BUILDING 106 FROM DRIVEWAY. WALKWAY AND STEPS TO FRONT DOOR ARE VISIBLE AT RIGHT PHOTO CENTER. EAST SIDE OF THE HOUSE (FORMER FRONT) ORIGINALLY WAS A FULL-LENGTH PORCH WHICH WAS LATER REMODELED INTO THE INTERIOR ROOMS. SWITCHRACKS OF CONTROL STATION ARE VISIBLE BEHIND THE HOUSE. VIEW TO SOUTHWEST.
- CA-145-1-D-4 EXTERIOR OF SOUTH SIDE OF BUILDING 106. VIEW TO NORTH.
- CA-145-1-D-5 EXTERIOR DETAIL OF SOUTH SIDE OF BUILDING 106 SHOWING ATTIC WINDOW FLANKED BY LOUVERED VENTS AT TOP PHOTO CENTER, AND REPLACEMENT SLIDING-GLASS WINDOWS ON TWO LOWER WINDOWS. BATHROOM WINDOW (PHOTO LEFT) HAS ORIGINAL WOOD SURROUNDS. WINDOW AT PHOTO RIGHT IS MODERN AND PART OF THE REMODELED FORMER PORCH AREA. VIEW TO NORTHEAST.

BISHOP CREEK HYDROELECTRIC SYSTEM,  
CONTROL STATION,  
WORKER COTTAGE (BUILDING 106)  
HAER No. CA-145-1-D  
INDEX TO PHOTOGRAPHS (Page 2)

- CA-145-1-D-6 EXTERIOR DETAIL SHOWING ASBESTOS SIDING COVERING ORIGINAL CLAPBOARD. STYLE OF BASEMENT VENT SURROUND WITH FLARING LENTIL IS REPEATED ON ORIGINAL DOORS AND WINDOWS. VIEW TO NORTH.
- CA-145-1-D-7 INTERIOR OF LIVING ROOM SHOWING FLUSH FRONT DOOR AT PHOTO CENTER, MODERN SIDING WINDOW ON EAST WALL (FORMER PORCH) AT PHOTO CENTER RIGHT, AND ORIGINAL PAIRED 6-LIGHT OVER 1-LIGHT WINDOWS ON NORTH WALL (PHOTO LEFT). VIEW TO NORTHEAST.
- CA-145-1-D-8 INTERIOR OF LIVING ROOM SHOWING OPEN DOOR TO KITCHEN NEXT TO BRICKED HEATER ENCLAVE (PHOTO CENTER), AND OPEN DOOR TO BEDROOM NO. 2 AT PHOTO LEFT. VIEW TO WEST.
- CA-145-1-D-9 INTERIOR OF KITCHEN SHOWING OPEN DOOR TO LIVING ROOM, AND BUILT-IN CABINETS AROUND SINK AND FLANKING 1-LIGHT OVER 1-LIGHT WINDOW. VIEW TO NORTHEAST.
- CA-145-1-D-10 INTERIOR OF KITCHEN SHOWING BUILT-IN CABINETS AND WIDE DOORWAY TO UTILITY ROOM AT BACK OF KITCHEN (PHOTO LEFT). VIEW TO NORTH.
- CA-145-1-D-11 INTERIOR OF UTILITY ROOM AT BACK OF KITCHEN SHOWING ROW OF WINDOWS. VIEW TO NORTHWEST.
- CA-145-1-D-12 INTERIOR OF UTILITY ROOM SHOWING BACK DOOR, BUILT-IN CABINETS, AND WASHER/DRYER PLUMBING AND VENT CONNECTIONS. VIEW TO SOUTHWEST.
- CA-145-1-D-13 INTERIOR OF BEDROOM NO. 1 SHOWING OPEN DOOR TO KITCHEN AT PHOTO LEFT, OPEN DOOR TO WALK-IN CLOSET AT PHOTO CENTER, AND OPEN DOOR TO BATHROOM AT PHOTO RIGHT. VIEW TO NORTHEAST.
- CA-145-1-D-14 INTERIOR OF BEDROOM NO. 1 SHOWING ORIGINAL 6-LIGHT OVER 1-LIGHT WINDOWS ON SOUTH AND WEST WALLS. VIEW TO SOUTHWEST.

BISHOP CREEK HYDROELECTRIC SYSTEM,  
CONTROL STATION,  
WORKER COTTAGE (BUILDING 106)  
HAER No. CA-145-1-D  
INDEX TO PHOTOGRAPHS (Page 3)

- CA-145-1-D-15 INTERIOR OF BATHROOM SHOWING OPEN DOOR TO BEDROOM NO. 2 AND SINK WITH UNUSUAL VANITY WINGS. VIEW TO NORTHEAST.
- CA-145-1-D-16 INTERIOR OF BATHROOM SHOWING OPEN DOOR TO BEDROOM NO. 1 AND MODERN SHOWER/BATH. VIEW TO SOUTHWEST.
- CA-145-1-D-17 INTERIOR OF BEDROOM NO. 2 SHOWING OPEN DOOR TO LIVING ROOM AT PHOTO RIGHT, OPEN DOOR TO WALK-IN CLOSET AT PHOTO CENTER RIGHT, AND OPEN DOOR TO BATHROOM AT PHOTO CENTER. VIEW TO WEST.
- CA-145-1-D-18 INTERIOR TO BEDROOM NO. 2 SHOWING DECORATIVE TREATMENT ON ORIGINAL WOOD DOOR SURROUNDS. VIEW TO WEST..
- CA-145-1-D-19 INTERIOR OF BEDROOM NO. 2 SHOWING BUILT-IN CABINETS ALONG EAST WALL. THIS PORTION OF THE BEDROOM WAS EXTENDED IN REMODELING THAT INCORPORATED THE FRONT PORCH INTO THE INTERIOR HOUSE. VIEW TO SOUTHEAST.