

# HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

HABS No. HI-206  
(Page 2)

U.S. NAVAL BASE, PEARL HARBOR, MINE SCHOOL BUILDING  
(U.S. Naval Base, Pearl Harbor, Naval Magazine Lualualei, West Loch  
Branch, Mine Mechanism Testing Building)  
(Quality Evaluation Lab, Facility 40)  
D Avenue, near the intersection of 3<sup>rd</sup> Street  
Pearl Harbor  
Honolulu County  
Hawaii

ADDENDUM TO  
U.S. NAVAL BASE, PEARL HARBOR, MINE MECHANISM TESTING BUILDING  
(U.S. Naval Base, Pearl Harbor, Naval Magazine Lualualei, West Loch Branch)  
(Quality Evaluation Lab, Building 40)  
D Avenue, near the intersection of 3<sup>rd</sup> Street  
Pearl Harbor  
Honolulu County  
Hawaii

David Franzen, Photographer

January 2009

Photographs numbered 1 through 3 for this facility were previously transmitted to the Library of Congress as part of a separate report, HABS No. HI-206 (December 1994).

The Record Name of this facility reflects the historic name and not the name by which it was known when first recorded. This facility was referred to as a Mine School from the time it was built in 1942 until at least 1948.

- |          |   |
|----------|---|
| HI-206-4 | OBLIQUE VIEW OF NORTHEAST END WITH CRANE IN FOREGROUND. VIEW FACING SOUTH.                                  |
| HI-206-5 | SOUTHWEST ELEVATION. VIEW FACING NORTH  |
| HI-206-6 | NORTHWEST WALL WITH ADDITION HOUSING ELECTRICAL AND VENTILATION EQUIPMENT. VIEW FACING EAST.                |
| HI-206-7 | LANAI ON SOUTHEAST SIDE. VIEW FACING NORTHEAST.   |
| HI-206-8 | INTERIOR OF SOUTHEAST WALL, SCREENED AT THE TOP, LOOKING TOWARDS NORTHEAST END WALL. VIEW FACING NORTHEAST. |

U.S. NAVAL BASE, PEARL HARBOR, MINE MECHANISM TESTING BUILDING  
(Facility 40)  
HABS No. HI-206  
INDEX TO PHOTOGRAPHS (Page 3)

- HI-206-9 INTERIOR OF BUILDING FROM THE NORTHEAST END. VIEW FACING SOUTHWEST
- HI-206-10 INTERIOR VIEW OF ORIGINAL ANCHOR AND PLUMMET WIND ROOM TRAVERSING NORTHEAST END OF BUILDING. CLOSED SLIDING DOOR LEADS TO INSET LANAI. VIEW FACING EAST.
- HI-206-11 INTERIOR LOOKING TOWARDS ENTRY FROM INSET LANAI. VIEW FACING SOUTH.
- HI-206-12 INTERIOR OF FORMER ARMORY SHOWING PARTITION WALLS, ORIGINAL AWNING WINDOWS. VIEW FACING NORTHWEST.
- HI-206-13 BATHROOM SINK WITH ORIGINAL FIXTURES. VIEW FACING SOUTH.

Photo Key Below

