5745 STOW LILBURN R 04 0027801R PILOT <C130B> ARCFT SN60-0298 DESTROYED.

DATE OF INCIDENCE- 26D68.

PLACE OF INCIDENCE- HIT AT 1616N-10714E, SVN. DOWN SAME LOCATION.

FACTS- TERRY 605 WAS ON AN ALR MISSION IN SVN. ACRFT SUSTAINED HITS IN THE TAIL SECTION FROM GROUND FIRE WHILE ON A AIR DROP MISSION. UNSUCCESSFUL ATTEMPT TO JETTISON CARGO WAS OBSERVED.

FINDINGS- COMBAT LOSS DUE TO HOSTILE ACTION.

STATUS- AS OF MAY 8 1968. END OF REPORT.

ALL ABOARD THIS ACRFT WERE KILLED THEY WERE- MAJ. STOW, JAMES MCKINSTRY 5556
03 3095699V <CP>, JOHN L MCDANIEL 04 0057547R, BERYL BLAYLOCK E5 <FE>
14616621, KENNETH JOHNSON E3 17732674 <LM>, AND [redacted] 5802

AFLC COMMENTS- RECORDS IN THIS OFFICE REFLECT TWO OTHER CREW MEMBERS ON BOARD AND BOTH KILLED- THEY WERE- RUSSELL R. RYAN E6 16382229 <AP> AND DANIEL J.OCONNOR E4 17455382 <AP>. THE REMAINS THAT HAVE BEEN RECOVERED AND RETURNED TO CONUS ARE- RYAN, OCONNOR, MCKINSTRY, BLAYLOCK, AND JOHNSON. THE REMAINS OF STOW AND MCDANIEL HAVE NOT BEEN RECOVERED.

CONTINUATION
PAGE 2/2

REFNO: 1146

NAME: LILBURN RAY STOW, USAF

LEAD(S)	COUNTRY	ADDRESS	COMMENTS
12516	VIETNAM	HUE CITY	LEAD'S SISTER TOLD AN INTERMEDIARY HER BROTHER HA RECOVERED THE ALLEGED REMAINS OF A U.S. SERVICEMAN AF ONE KILOMETER SOUTH OF A LUOI AIRFIELD (YC3899), THUA PROVINCE. JCRC LIAISON BANGKOK TH MSG 270959Z MAR 90.