

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
PA
46-AMB,
8-

FIRST NATIONAL BANK OF AMBLER
30 East Butler Avenue
Ambler
Montgomery County
Pennsylvania

HABS NO. PA-6031

James Scott, photographer, July 1994

- PA-6031-1 PERSPECTIVE VIEW OF REAR OF BUILDING TAKEN FROM THE SOUTHWEST
- PA-6031-2 ELEVATION VIEW OF REAR FACADE TAKEN FROM THE SOUTH WITHOUT SCALE
- PA-6031-3 ELEVATION VIEW OF FRONT FACADE TAKEN FROM THE SOUTH WITHOUT SCALE
- PA-6031-4 PERSPECTIVE VIEW TAKEN FROM THE NORTHEAST
- PA-6031-5 VIEW OF LOBBY TAKEN FROM NORTHEAST CORNER OF BUILDING
- PA-6031-6 VIEW OF BALUSTRADE AND SOUTH WALL AND BALCONY TAKEN FROM NORTH BALCONY
- PA-6031-7 VIEW OF BALUSTRADE AND SOUTH WALL AND BALCONY TAKEN FROM NORTH BALCONY OVER RAIL
- PA-6031-8 VIEW OF LOBBY TAKEN FROM THE NORTHEAST CORNER OF NORTH BALCONY
- PA-6031-9 CLOSEUP OF BANK CLOCK'S OPERATING MECHANISM. CLOCK IS ON THE NORTH WALL.
- PA-6031-10 CLOSEUP OF BANK CLOCK'S OPERATING MECHANISM. CLOCK IS ON THE NORTH WALL.
- PA-6031-11 CLOSEUP SHOT OF HANDLE ON RADIATOR LOCATED ON THE NORTH WALL OF NORTH BALCONY