

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

WILLIAMS FIELD, HANGAR COMPLEX, HANGART-38 HABS AZ-208-F
(Williams Gateway Airport, Building T-38)
6001 South Power Road
Mesa
Maricopa County
Arizona

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Brian Grogan, photographer, June 1996

- | | |
|-------------|---|
| AZ-208-F-1 | View of side building T-38, seen from apron. Looking 306 degrees NW. |
| AZ-208-F-2 | Perspective view of side and end of building T-38. Looking WSW. |
| AZ-208-F-3 | Detail of side of building T-38, showing concrete wall buttresses. Looking N. |
| AZ-208-F-4 | Perspective view of side and end of building T-38, showing shed addition for office space. Looking 186 degrees S. |
| AZ-208-F-5 | View of end of building T-38, seen from inside building T-37. Looking 220 degrees SW. |
| AZ-208-F-6 | View of end of building T-38, seen from end of building T-37. Looking 220 degrees SW. |
| AZ-208-F-7 | Interior View of building T-38, seen from SW corner. Looking 40 degrees NE. |
| AZ-208-F-8 | Interior View of building T-38, seen from NE corner. Looking 258 Degrees WSW. |
| AZ-208-F-9 | Detail of north end of building T-38. Note curtain mechanism at top center of truss. Looking 216 degrees SW. |
| AZ-208-F-10 | Detail of NW corner, showing hinged connection between truss and buttressed concrete wall. Looking 256 degrees W. |

WILLIAMS FIELD, HANGAR COMPLEX, HANGART-38
HABS AZ-208-F
INDEX TO PHOTOGRAPHS

- AZ-208-F-11 Interior Detail, showing roof construction. Looking 121 degrees SE.
- AZ-208-F-12 Interior detail, showing center line with hinged connections of trusses. Looking 216 degrees SW.
- AZ-208-F-13 Interior detail, showing line of hinged connections between trusses and buttressed concrete wall. Looking 258 degrees W.
- AZ-208-F-14 Interior View, showing roof construction detail. Looking 126 degrees SE.
- AZ-208-F-15 Interior view, showing roof construction detail with painted building number. The building number is also seen in the lower left of photograph AZ-208-F-14. Looking 126 degrees SE.
- AZ-208-F-16 Interior wall detail, showing hinged connection between truss and concrete wall consisting of concrete posts and beams with wall space filled with cinder blocks from a later renovation. Looking 126 degrees SE.
- AZ-208-F-17 Interior Wall detail of building T-37, showing original wall treatment not seen in building T-38. Note fiber board panel between concrete posts. Looking 306 degrees NW.
- AZ-208-F-18 Interior detail of building T-37, showing hanging lamp installation pattern not seen in building T-38. Looking 92 degrees E.
- AZ-208-F-19 Interior detail of floor markings and aircraft ground stakes on floor of building T-38. Seen from center of south wall. Looking 310 degrees NW.
- AZ-208-F-20 Insignia of 82nd flying training wing painted on floor of building T-38.
- AZ-208-F-21 Photograph of drawing for building T-38, dated April 1945 (Source: Williams Air Force Base). MILITARY CONSTRUCTION, WILLIAMS FIELD, CHANDLER, ARIZONA, CONVERSION OF HANGARS TO PLM AND APPURTENANCES.

WILLIAMS FIELD, HANGAR COMPLEX, HANGART-38
HABS AZ-208-F
INDEX TO PHOTOGRAPHS

- AZ-208-F-22 Photograph of drawing for building T-38, dated 21 April 54
(Source: Williams Air Force Base). SITE PLAN & BASIC
CONST. DETAILS OF HANGARS (SHEET 2 OF 3).
- AZ-208-F-23 Photograph of drawing for building T-38, dated 21 April 54
(source: Williams Air Force Base). SITE PLAN & BASIC
CONST. DETAILS OF HANGARS (SHEET 3 OF 3).