

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
SC
8-HUG.V.
2

Addendum to:
POMPION HILL CHAPEL
Cooper River, south side
Huger Vicinity
Berkeley County
South Carolina

HABS No. SC-34
(Page 4)

1

Photos SC-34-1 through SC-34-30 were previously transmitted to the Library of Congress.

The photos below were taken between May and October 1980 for the 1980 South Carolina project made possible by grants from the National Endowment for the Arts. Charles N. Bayless, AIA, was the photographer.

SC-34-31 9	Southeast corner
SC-34-32 10	East side
SC-34-33 11	East side, Palladian window detail
SC-34-34 12	Northwest corner
SC-34-35 13	Southwest corner
SC-34-36 14	South entry
SC-34-37 15	South side, west jamb, showing completion date
SC-34-38 16	South side, entry, east jamb, showing mason's marks
SC-34-39 17	Nave, looking east
SC-34-40 18	Chancel
SC-34-41 19	Palladian window detail, interior
SC-34-42 20	Nave, looking west
SC-34-43 21	Nave, looking northeast

POMPION HILL CHAPEL
HABS No. SC-34
INDEX TO PHOTOGRAPHS
(Page 8)

2

SC-34-44 ²⁰	Nave, looking south
SC-34-45 ²³	Pulpit
SC-34-46 ²⁴	Pulpit detail
SC-34-47 ²⁵	Pulpit teaster soffit
SC-34-48 ²⁶	Simons memorial
SC-34-49 ²⁷	Northeast corner, exterior damage
SC-34-50 ²⁸	West ceiling damage
SC-34-51 ²⁹	Northeast corner, interior damage
SC-34-52 ³⁰	North wall, damage above door