

Rosemary Inn, Lodge (Bldg. No. 372)
Olympic National Park
Barnes Point, Lake Crescent
Port Angeles Vicinity
Clallam County
Washington

HABS No. WA-185-A

HABS
WASH
5-POAN.V,
2A-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Building Survey
National Park Service
Western Region
Department of the Interior
San Francisco, California 94107


HABS
WASH
5-POAN.Y,
2A-

NATIONAL PARK SERVICE
Department of the Interior

HISTORIC AMERICAN BUILDING SURVEY
ARCHITECTURAL DATA FORM

STATE WASHINGTON	COUNTY CLALLAM	TOWN OR VICINITY Approximately 20 miles southwest of Port Angeles
HISTORIC NAME OF STRUCTURE (include source for name) Rosemary Inn; Lodge (Historic Resource Study (HRS) 1983)		HABS NO. WA-185-A
SECONDARY OR COMMON NAMES OF STRUCTURE		
COMPLETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park.		
DATE OF CONSTRUCTION (include source) c.1914 - 1930s (HRS, 1983)	ARCHITECT(S) (include source) Builder and Craftsman: John Daum (HRS, 1983)	
SIGNIFICANCE (architectural and historical, include original use of structure) Rosemary Inn is historically significant as a representative example of one of a dozen Lake Crescent resorts popular between the 1890s and 1920s. The inn was built on one of the earliest settled tracts of land around the lake. It is associated with events that contributed to resort development on the Olympic Peninsula, with the creation of Olympic National Park and with figures important in the National Park movement. Architecturally, the inn exhibits a high degree of craftsmanship and integrity.		
STYLE (if appropriate) "Craftsman-style" resort lodge		
MATERIAL OF CONSTRUCTION (include structural systems) Wood-frame construction set on post and pier foundation		
SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Irregular shape: overall dimensions 86' x 34' with 41' x 38' extension on SE corner.		
EXTERIOR FEATURES OF NOTE 1 1/2 - stories; wood-shingled gable roof with shed roof dormers on north and south; slightly extended eaves with exposed rafters and plain fascia boards; wood shingle siding with vertical wood board siding above (at gable ends); corner boards; multi-paned double-hung and casement sash; numerous shed-roof porch overhangs extended from main body, supported by peeled logs and squared posts; vertical wood board skirting beneath plain wood sill board.		
INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Massive stone and mortar fireplace in lobby; hand-crafted twisted madrona baluster on first floor stairway; hardwood floors; wood wainscoting along walls in lobby with horizontal knotty pine boards above windows; wood ceiling on 1st floor.		
MAJOR ALTERATIONS AND ADDITIONS, WITH DATES East and west wings added c.1930s; alteration alteration of porch on main (north) facade (date unknown); interior modifications (1988); new foundation (1988); new addition connected by breezeway on south (1988)		
PRESENT CONDITION AND USE Excellent condition; seasonal educational facility		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983		
COMPILER, AFFILIATION Gretchen A. Luxenberg, National Park Service	DATE July, 1988	

ROSEMARY INN, LODGE (Bldg. No. 372)
HABS No. WA-185-A (page 2)



Rosemary Lodge Building #372 - First Floor

