

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER  
ARIZ  
11-COOL,  
1H-

San Carlos Irrigation Project,  
Pima Lateral  
Main Canal to Sacaton Dam  
~~Vicinity of~~ Coolidge  
Pinal County  
Arizona

HAER No. AZ-50-H

Bob Knotts, photographer, June 1995

- AZ-50-H-1            LOOKING EAST TOWARDS HEAD OF PIMA LATERAL
- AZ-50-H-2            VIEW OF CHECK-DROP STRUCTURE AT STATION 198+00  
LOOKING SOUTH
- AZ-50-H-3            VIEW OF CHECK-DROP STRUCTURE AT STATION 292+00  
LOOKING EAST
- AZ-50-H-4            VIEW OF CHECK-DROP STRUCTURE AT STATION 292+00  
LOOKING WEST
- AZ-50-H-5            VIEW LOOKING WEST AT BRIDGE OVER PIMA LATERAL AT  
CHRISTENSEN ROAD
- AZ-50-H-6            DETAIL OF BRIDGE OVER PIMA LATERAL AT CHRISTENSEN  
ROAD
- AZ-50-H-7            TURNOUT TO BLACKWATER LATERAL ON PIMA LATERAL IN  
T5S, R8E, & S16/17. VIEW LOOKING NORTHEAST
- AZ-50-H-8            WELL ON PIMA LATERAL IN T5S, R8E, & S17
- AZ-50-H-9            PARSHALL FLUME ON PIMA LATERAL, T5S, R7E, S12. VIEW  
LOOKING SOUTHEAST
- AZ-50-H-10           DROP STRUCTURES ON PIMA LATERAL, T4S, R7E, S29? VIEW  
LOOKING EAST.
- AZ-50-H-11           TURNOUT TO LITTLE GILA (CASA BLANCA) CANAL ON PIMA  
LATERAL IN T4S, R6E, S24. VIEW LOOKING WEST

San Carlos Irrigation Project ,  
Pima Lateral  
HAER No. AZ-50-H  
Index to Photographs (page 2)

- AZ-50-H-12      Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1925. Vol. I, Narrative and Photographs, Irrigation District #4, California and Southern Arizona, RG 75, Entry 655, Box 28, National Archives, Washington, DC.) Photographer unknown. PIMA LATERAL, LINING EQUIPMENT, 5/13/25
- AZ-50-H-13      Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1926. Vol. I, Narrative and Photographs, RG 75, Entry 655, Box 29, National Archives, Washington, DC.) Photographer unknown. PIMA LATERAL DROP NEAR KENILWORTH, 5/10/26
- AZ-50-H-14      Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1927. Vol. I, Narrative and Photographs, District #4, RG 75, Entry 655, Box 29, National Archives, Washington, DC.) Photographer unknown. PIMA LATERAL, MCCLELLAN CONDUIT, ENTRANCE BEFORE POURING THE CONDUIT, 4/30/27
- AZ-50-H-15      Photographic copy of photograph. (Source: U.S. Department of Interior. Office of Indian Affairs. Indian Irrigation Service. Annual Report, Fiscal Year 1927. Vol. I, Narrative and Photographs, District #4, RG 75, Entry 655, Box 29, National Archives, Washington, DC.) Photographer unknown. PIMA LATERAL, MCCLELLAN WASH CONDUIT, LOOKING SOUTH-WEST, 4/16/27
- AZ-50-H-16      Photographic copy of drawing, dated September 1924, in possession of San Carlos Irrigation Project. United States Indian Service, Irrigation. PIMA LATERAL HEADWORKS, RADIAL GATES