

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

WILLIAMS FIELD, HANGAR COMPLEX, HANGAR S-25
(Williams Gateway Airport, Building S-25)
6001 South Power Road
Mesa
Maricopa County
Arizona

HABS AZ-208-B

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Michael Corbett, photographer, June 1996

- | | |
|------------|--|
| AZ-208-B-1 | Front of building S-25 seen from rear of building S-24. Looking 266 degrees W. |
| AZ-208-B-2 | Perspective view of front and side of building S-25. Looking 234 degrees SW. |
| AZ-208-B-3 | Detail of north side showing exhaust vent, corrugated metal siding, and windows. Looking 180 degrees S. |
| AZ-208-B-4 | Perspective view of rear showing doors to furnace room at center, and chimney above furnace room at center. Looking 136 degrees SE. |
| AZ-208-B-5 | Perspective view of rear and south walls, seen from front street. Looking 22 degrees NNE. |
| AZ-208-B-6 | Detail of door panels, front of building S-25, with pilot door in right panel. Looking 266 degrees W. |
| AZ-208-B-7 | Detail of interior of door panels. Looking 68 degrees E. |
| AZ-208-B-8 | Detail view of wheel assembly (wheel, and wheel cover marked "Allith") on steel rails, drainage gates, and interior of door panel. Looking 68 degrees E. |
| AZ-208-B-9 | Interior view of door pocket and steel rails for door panels. Looking N. |

WILLIAMS FIELD, HANGAR COMPLEX, HANGAR S-25
HABS AZ-208-B
INDEX TO PHOTOGRAPHS

- AZ-208-B-10 Interior view from NE corner, showing steam pipes and heaters attached to lower chords of trusses, and top guides for door panels. Looking 210 degrees SSW.
- AZ-208-B-11 Interior view from SE corner , showing rear wall and roof structure. Looking 308 degrees NW.
- AZ-208-B-12 Interior view from SW corner, showing paint barn in left corner. Looking 350 degrees N.
- AZ-208-B-13 Interior detail of north wall, showing wall construction, windows, and suspended ceiling lamp. Looking 2 degrees N.
- AZ-208-B-14 Interior detail of SW rear wall and ceiling, showing wall construction, windows, girder and truss joints, roof support members and suspended ceiling lamp. Looking 238 degrees SW.
- AZ-208-B-15 Interior detail of girder and truss joint, and hanging lamp. Looking up.
- AZ-208-B-16 Interior detail of rear wall construction, showing brick fire wall, steel columns, wood framing between columns, and windows. Looking 258 degrees W.
- AZ-208-B-17 Interior detail of south wall, showing steel columns, wood framing between columns, cross bracing , and windows. Looking 178 degrees S.
- AZ-208-B-18 Interior detail of rear wall, showing wall surface of paperboard and battens, and doors to office and lavatory. Note "Corrosion control" sign painted on wall. Looking 268 degrees W.
- AZ-208-B-19 Interior detail of office, showing steam radiator. Linoleum floor, baseboard, and acoustical tile ceiling. Looking 268 degrees.
- AZ-208-B-20 Interior detail, showing boiler located in shed addition at rear. See photograph AZ-208-B-4 which shows doors to furnace room. Looking 204 degree SSW from doorway.
- AZ-208-B-21 Photograph of drawing for Builder S-25, dated Jan 68 (Source: Williams Air force Base). Maint Field Hangar Building S-25.