

HISTORIC AMERICAN ENGINEERING RECORD  
INDEX TO PHOTOGRAPHS

HAER  
CAL  
14-BISH.V  
59-

**Bishop Creek Hydroelectric System, Plant 4**  
**Worker Cottage (Building 116)**  
**Bishop Creek**  
**Bishop Vicinity**  
**Inyo County**  
**California**

**HAER No. CA-145-4-G**

Gregory L. O'Loughlin, photographer

April, 1997

- CA-145-4-G-1 EXTERIOR OVERVIEW OF PLANT 4 RESIDENTIAL COMPLEX SHOWING BUILDING 116 AT RIGHT PHOTO CENTER, SECOND HOUSE FROM THE END ON THE FAR (WESTERN) SIDE OF THE STREET. VIEW TO WEST.
- CA-145-4-G-2 EXTERIOR NORTH CORNER OF BUILDING 116 (FOREGROUND) WITH BUILDING 117 IN THE BACKGROUND. BUILDINGS 116 AND 117 ARE NEAR MIRRORS OF EACH OTHER. VIEW TO NORTHWEST.
- CA-145-4-G-3 EXTERIOR OF BUILDING 116 SHOWING FRONT PORCH ENTRY ON SOUTH EAST SIDE OF HOUSE, REAR ENTRY AND CURVED PROJECTING COVER ON SOUTHWEST SIDE. VISIBLE PORTION OF BUILDING IN THIS PHOTO IS THE ORIGINAL, HIPPED-ROOF HOUSE. VIEW TO NORTH.
- CA-145-4-G-4 EXTERIOR OF FRONT ENTRY PORCH SHOT FROM SLIDING-GLASS ENTRY DOOR. VIEW TO NORTHEAST.
- CA-145-4-G-5 EXTERIOR OF NORTH CORNER OF HOUSE SHOWING 1966 GABLE-ROOFED ADDITION. VIEW TO SOUTH.
- CA-145-4-G-6 EXTERIOR OF WEST CORNER OF HOUSE SHOWING REAR ALLEY AND BASEMENT ENTRY (DELINEATED BY WELDED-PIPE HANDRAILS). NOTE BLACK STAIN ON ROOF FROM CHIMNEY ASHFALL. VIEW TO EAST.
- CA-145-4-G-7 INTERIOR OF BASEMENT SHOWING HOT-WATER HEATER, INSULATION, AND FOUNDATION SUPPORTS. VIEW TO EAST.

BISHOP CREEK HYDROELECTRIC SYSTEM, PLANT 4,  
WORKER COTTAGE (BUILDING 116  
HAER No. CA-145-4-G  
INDEX TO PHOTOGRAPHS (Page 2)

- CA-145-4-G-8 INTERIOR OF LIVING ROOM SHOWING SLIDING-GLASS FRONT ENTRY, SMOOTH REFINISHED WALLS, AND SLIDING-GLASS WINDOWS ON 1966 ADDITION PORTION OF ROOM. VIEW TO EAST.
- CA-145-4-G-9 INTERIOR OF LIVING ROOM SHOWING CEILING BEAM SEPARATING ORIGINAL PORTION OF LIVING ROOM (BACKGROUND) FROM 1966 ADDITION. DOOR AT PHOTO CENTER LEADS TO KITCHEN; DOOR AT PHOTO RIGHT LEADS TO BEDROOM NO. 2; SLIDING-GLASS FRONT ENTRY DOOR AT PHOTO LEFT. VIEW TO SOUTHWEST.
- CA-145-4-G-10 INTERIOR OF REMODELED KITCHEN SHOWING 1950s STYLE CABINETS AROUND REPLACEMENT SINK, AND ORIGINAL 3-LIGHT OVER 3-LIGHT, DOUBLE-HUNG, WOOD-FRAMED WINDOW. VIEW TO EAST.
- CA-145-4-G-11 INTERIOR OF KITCHEN SHOWING BUILT-IN CABINETS AND ENTRY DOOR FROM LIVING ROOM. VIEW TO EAST.
- CA-145-4-G-12 INTERIOR OF KITCHEN SHOWING DINING AREA, PANELED AND GLAZED ORIGINAL REAR DOOR, AND TWO PAIRS OF ORIGINAL 6-LIGHT OVER 1-LIGHT, DOUBLE-HUNG, WOOD-FRAMED WINDOWS. VIEW TO SOUTH.
- CA-145-4-G-13 INTERIOR OF BEDROOM NO. 1 SHOWING OPEN DOORS FROM KITCHEN (AT PHOTO RIGHT) AND BATHROOM (AT PHOTO LEFT). REMODELED CLOSET IS VISIBLE BEHIND ENTRY DOOR FROM KITCHEN. NOTE ORIGINAL DECORATIVE WOOD STRIPPING ON WALLS. VIEW TO EAST.
- CA-145-4-G-14 INTERIOR OF BEDROOM NO. 1 SHOWING ORIGINAL 6-LIGHT OVER 1-LIGHT, DOUBLE-HUNG, WOOD-FRAMED WINDOWS. VIEW TO WEST.
- CA-145-4-G-15 INTERIOR OF REMODELED BATHROOM SHOWING OPEN DOOR FROM BEDROOM NO. 1 AND REPLACEMENT SLIDING-GLASS WINDOW IN ORIGINAL WOOD FRAME AT PHOTO RIGHT. VIEW TO WEST.
- CA-145-4-G-16 INTERIOR OF BATHROOM SHOWING OPEN DOOR TO BEDROOM NO. 2. VIEW TO NORTH.

BISHOP CREEK HYDROELECTRIC SYSTEM, PLANT 4,  
WORKER COTTAGE (BUILDING 116  
HAER No. CA-145-4-G  
INDEX TO PHOTOGRAPHS (Page 3)

- CA-145-4-G-17 INTERIOR OF BEDROOM NO. 2 SHOWING OPEN DOORS FROM LIVING ROOM (PHOTO LEFT) AND BATHROOM (PHOTO RIGHT). NOTE REMODELED CLOSET ADJACENT TO ENTRY DOOR FROM LIVING ROOM, AND ORIGINAL DECORATIVE WOOD STRIPPING ON WALLS AND CEILING. VIEW TO SOUTH
- CA-145-4-G-18 INTERIOR OF BEDROOM NO. 2 SHOWING ORIGINAL 6-LIGHT OVER 1-LIGHT, DOUBLE-HUNG, WOOD-FRAMED WINDOW ON NORTHWEST WALL AT PHOTO RIGHT. VIEW TO WEST.
- CA-145-4-G-19 INTERIOR OF BEDROOM NO. 3 SHOWING ENTRY DOOR FROM BEDROOM NO. 2 AT PHOTO LEFT ADJACENT TO BUILT-IN CLOSET ON SOUTHWEST WALL. VIEW TO SOUTHWEST.
- CA-145-4-G-20 INTERIOR OF BEDROOM NO. 3 SHOWING SLIDING-GLASS WINDOWS. VIEW TO NORTH.