

# HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

Douglas Missile Test Facility, Sigma Test Complex  
West of Security Park Drive  
Rancho Cordova  
Sacramento County  
California

HAER No. CA-2310-E

Robert A. Hicks, Photographer, March, 2013

Note: Photographs are contact prints from 4" x 5" negatives.

- CA-2310-E-1      CONTEXTUAL VIEW OF A PORTION OF THE SIGMA TEST AREA SHOWING, FROM LEFT TO RIGHT, THE PERSONNEL BUNKER (ON EXTREME LEFT), THE ASSEMBLY BUILDING AND THE HOT CONDITIONING CHAMBER; VIEW TO NORTHWEST.
- CA-2310-E-2      ELEVATED VIEW OF THE COLD CONDITIONING CHAMBER'S CONCRETE PAD AND THE EAST ELEVATION OF THE HOT CONDITIONING CHAMBER. NOTE THE ASSEMBLY BUILDING'S ROOF AND EARTHEN REVETMENT CAN BE SEEN ON THE LEFT HORIZON OF THE PHOTOGRAPH; VIEW TO WEST.
- CA-2310-E-3      SOUTH AND WEST ELEVATIONS OF THE HOT CONDITIONING CHAMBER; VIEW TO NORTH NORTHEAST.
- CA-2310-E-4      ELEVATED VIEW OF ASSEMBLY BUILDING'S WEST AND SOUTH ELEVATIONS. NOTE BUILDING AND PAVED YARD SURROUNDED WITH EARTHEN REVETMENTS; VIEW TO NORTHEAST.
- CA-2310-E-5      ELEVATED OBLIQUE VIEW OF THE ASSEMBLY BUILDING'S NORTH AND WEST ELEVATIONS. NOTE SERIES OF ATTACHED SHED STRUCTURES ON NORTH WALL; VIEW TO SOUTHEAST.
- CA-2310-E-6      OBLIQUE VIEW OF THE ASSEMBLY BUILDING'S NORTH AND EAST ELEVATIONS; VIEW TO SOUTHWEST.
- CA-2310-E-7      INTERIOR VIEW OF ASSEMBLY BUILDING. NOTE OVERHEAD RAIL FOR PORTABLE HOIST IN FOREGROUND; VIEW TO EAST.
- CA-2310-E-8      OBLIQUE VIEW OF THE PERSONNEL BUNKER'S WEST AND SOUTH ELEVATIONS. NOTE THAT A PORTION OF THE ASSEMBLY BUILDING AND ITS SOUTHERN EARTHEN REVETMENT IS EVIDENT ON RIGHT OF PHOTOGRAPH; VIEW TO NORTHEAST.

DOUGLAS MISSILE TEST FACILITY, SIGMA TEST COMPLEX  
HAER No. CA-2310-E  
INDEX TO PHOTOGRAPHS  
(Page 2)

- CA-2310-E-9      OBLIQUE VIEW OF THE PERSONNEL BUNKER'S EAST AND NORTH ELEVATIONS; VIEW TO WEST SOUTHWEST.
- CA-2310-E-10    INTERIOR VIEW OF PERSONNEL BUNKER. NOTE CABLE RACEWAYS FORMED IN CONCRETE FLOOR; VIEW TO NORTHEAST.
- CA-2310-E-11    ELEVATED VIEW OF EARTHEN REVETMENT SURROUNDING THE TEST AREA AND SUPPORT BUILDING; VIEW TO SOUTHWEST.
- CA-2310-E-12    ELEVATED VIEW OF TEST AREA; VIEW TO SOUTHEAST.
- CA-2310-E-13    ELEVATED VIEW OF TEST AREA STRUCTURES; VIEW TO NORTHWEST.