

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum To  
Decatur House  
748 Jackson Place, NW  
Washington  
District of Columbia

HABS No. DC-16

Photographs DC-16-1 through DC-16-15 have been transmitted to the Library of Congress.

Photographer Unknown, Date Unknown

- DC-16-16<sup>24</sup> EAST FRONT, VIEW FROM NORTHEAST
- DC-16-17<sup>25</sup> EAST FRONT, VIEW FROM NORTHEAST (AFTER RECONSTRUCTION OF ADJOINING BUILDINGS)
- DC-16-18<sup>26</sup> EAST FRONT, VIEW FROM SOUTHEAST
- DC-16-19<sup>27</sup> SOUTH SIDE OF SERVICE WING AND WEST (REAR) OF MAIN BLOCK
- DC-16-20<sup>28</sup> EAST FRONT, DETAIL OF ENTRANCE
- DC-16-21<sup>29</sup> EAST FRONT, DETAIL OF ENTRANCE AND FIRST FLOOR, FROM THE NORTHEAST
- DC-16-22<sup>30</sup> FIRST FLOOR, VIEW EAST TO ENTRANCE DOORWAY
- DC-16-23<sup>31</sup> FIRST FLOOR, ENTRANCE HALL, VIEW WEST TO STAIR AND REAR DOORWAY
- DC-16-24<sup>32</sup> FIRST FLOOR, STAIRHALL, VIEW WEST
- DC-16-25<sup>33</sup> FIRST FLOOR, NORTHEAST ROOM, VIEW TO NORTH WALL
- DC-16-26<sup>34</sup> FIRST FLOOR, SOUTHWEST ROOM, VIEW SOUTH
- DC-16-27<sup>35</sup> SECOND FLOOR, MAIN STAIR HALL
- DC-16-28<sup>36</sup> SECOND FLOOR, MAIN STAIR HALL, DETAIL OF PILASTER AND DOOR MOLDING
- DC-16-29<sup>37</sup> SECOND FLOOR, DRAWING ROOM, VIEW EAST
- DC-16-30<sup>38</sup> SECOND FLOOR, DRAWING ROOM, DETAIL OF PARQUET FLOORING, VIEW WEST

DECATUR HOUSE  
HABS No. DC-16  
INDEX TO PHOTOGRAPHS (2)

- DC-16-31<sup>39</sup> SECOND FLOOR, SOUTHWEST ROOM, VIEW SOUTHEAST  
DC-16-32<sup>40</sup> ATTIC, HALL, VIEW SOUTHWEST TO DOORWAY (BEFORE REMODELING)  
DC-16-33<sup>41</sup> ATTIC, HALL, VIEW NORTHEAST TO DOORWAY (BEFORE REMODELING)  
DC-16-34<sup>42</sup> ATTIC, HALL, VIEW SOUTHEAST TO DOORWAY (BEFORE REMODELING)  
DC-16-35<sup>43</sup> ATTIC, GENERAL VIEW TO SOUTHWEST (DURING REMODELING)  
DC-16-36<sup>44</sup> ATTIC, GENERAL VIEW TO SOUTHWEST CORNER (DURING REMODELING)  
DC-16-37<sup>45</sup> ATTIC, VIEW EAST TO SOUTHEAST CORNER  
DC-16-38<sup>46</sup> ATTIC, VIEW SOUTH TO SOUTHEAST END  
DC-16-39<sup>47</sup> ATTIC, TYPICAL OUTRIGGING FOR EAST AND WEST WALLS  
DC-16-40<sup>48</sup> ATTIC, TYPICAL OUTRIGGING , VIEW TURNING CORNER  
DC-16-41<sup>49</sup> ATTIC, TYPICAL OUTRIGGING FOR NORTH AND SOUTH WALLS  
DC-16-42<sup>50</sup> ATTIC, UPPER CRAWL SPACE  
DC-16-43<sup>51</sup> ATTIC, UPPER CRAWL SPACE, DETAIL OF QUEEN POST

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
DC,  
WASH,  
28-

ADDENDUM TO  
DECATUR HOUSE (NATIONAL TRUST FOR HISTORIC PRESERVATION)  
748 Jackson Place, NW  
Washington  
District of Columbia

HABS No. DC-16

DC-16-1 through DC-16-43 were transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, 1976

<sup>52</sup>  
DC-16-44 (CT)      EAST FRONT, VIEW FROM SOUTHEAST

# HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

ADDENDUM TO:  
DECATUR HOUSE  
National Trust for Historic Preservation, 748 Jackson Place  
Northwest  
Washington  
District of Columbia

HABS DC-16

Photographs Nos. 1-8 were taken as part of the Pictorial Archive of Early American Architecture (PAEAA) and accessioned into HABS. Photographs HABS No. DC-16-9 to DC-16-51 were transmitted previously to the Library of Congress.

## INDEX TO BLACK AND WHITE PHOTOGRAPHS

Renee Bieretz, photographer, February 2012

- |          |  |
|----------|--|
| DC-16-52 | Interior view, Slave Quarter/Service Wing, first floor, east end, east elevation of fireplace and chimney looking west   |
| DC-16-53 | Interior view, Slave Quarter/Service Wing, first floor, east end, east elevation, looking west, with scale   |
| DC-16-54 | Interior view, Slave Quarter/Service Wing, first floor, east end, perspective view of the east chimney looking northwest (note ghost of mantel, nailing block) |
| DC-16-55 | Interior view, Slave Quarter/Service Wing, first floor, east end, west elevation of the east chimney, looking east   |
| DC-16-56 | Interior view, Slave Quarter/Service Wing, first floor, east end, west elevation of the east chimney looking east, with scale                                  |
| DC-16-57 | Interior view, Slave Quarter/Service Wing, first floor, east end, perspective view of the east chimney looking southeast                                       |
| DC-16-58 | Interior view, Slave Quarter/Service Wing, first floor, east end, detail of bevel in chimneystack at the second-floor level                                    |
| DC-16-59 | Interior view, Slave Quarter/Service Wing, first floor, west end, north elevation of west chimney  |

DECATUR HOUSE  
HABS DC-16  
INDEX TO PHOTOGRAPHS

- DC-16-60 Interior view, Slave Quarter/Service Wing, first floor, west end, east elevation of west chimney
- DC-16-61 Interior view, Slave Quarter/Service Wing, first floor, west end, east elevation of west chimney, with scale
- DC-16-62 Interior view, Slave Quarter/Service Wing, first floor, west end, perspective view looking northeast
- DC-16-63 Interior view, Slave Quarter/Service Wing, first floor, west end, west elevation of west chimney
- DC-16-64 Interior view, Slave Quarter/Service Wing, first floor, west end, west elevation of west chimney, with scale
- DC-16-65 Interior view, Slave Quarter/Service Wing, first floor, west end, perspective view looking southeast
- DC-16-66 Interior view, Slave Quarter/Service Wing, first floor, west end, detail view looking up chimney flue
- DC-16-67 Interior view, Slave Quarter/Service Wing, first floor, west end, west chimney, view looking up flue, note domed shaped and ironwork
- DC-16-68 Interior view, Slave Quarter/Service Wing, second floor, east end, east elevation of chimney
- DC-16-69 Interior view, Slave Quarter/Service Wing, second floor, east end, east elevation of east chimney, with scale
- DC-16-70 Interior view, Slave Quarter/Service Wing, second floor, east end, perspective view of east chimney, looking northwest
- DC-16-71 Interior view, Slave Quarter/Service Wing, second floor, east end, west elevation of east chimney
- DC-16-72 Interior view, Slave Quarter/Service Wing, second floor, east end, west elevation of east chimney, with scale
- DC-16-73 Interior view, Slave Quarter/Service Wing, second floor, west end, east elevation of west chimney
- DC-16-74 Interior view, Slave Quarter/Service Wing, second floor, west end, east elevation of west chimney, with scale

DECATUR HOUSE  
HABS DC-16  
INDEX TO PHOTOGRAPHS

- DC-16-75 Interior view, Slave Quarter/Service Wing, second floor, west end, perspective view of west chimney, looking northeast
- DC-16-76 Interior view, Slave Quarter/Service Wing, second floor, west end, perspective view looking southeast
- DC-16-77 Interior view, Slave Quarter/Service Wing, second floor, west end, detail of west chimney to show scars in brickwork from the partition wall, view looking southeast at north elevation of chimney
- DC-16-78 Interior view, Slave Quarter/Service Wing, second floor, view looking north to show framing for hall partition wall
- DC-16-79 Interior view, Slave Quarter/Service Wing, second floor, detail view looking south to show joists and skylight and original sheathing for roof
- DC-16-80 Interior view, Slave Quarter/Service, second floor, detail view of framing to show joists (with ghosts of lathe) and header (trimmer) with keyed through tenon.