

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DC,
WASH
503-

Patent Office Building
(U. S. Civil Service Commission;
National Portrait Gallery; National
Museum of American Art)
Bounded by 7th, 9th, F, and G Streets, NW
Washington
District of Columbia

HABS No. DC-130

- No. 1: Ronald Comedy, Photographer 1969
Nos. 2-8, 12, 16-32: Jack E. Boucher, Photographer May 1968
Nos. 9-11, 13-15: Russell Jones, Photographer April 1963
- DC-130-1 SOUTH FRONT AND WEST SIDE
DC-130-2 INTERIOR COURTYARD, FROM THE EAST
DC-130-3 INTERIOR COURTYARD, FROM THE NORTHEAST
DC-130-4 DETAIL, SOUTH FRONT, PORTICO (ELEVATION)
DC-130-5 DETAIL, SOUTH FRONT, PORTICO (OBLIQUE VIEW FROM THE SOUTHWEST)
DC-130-6 DETAIL, SOUTH FRONT, PORTICO, VIEW BETWEEN ROWS OF COLUMNS
DC-130-7 DETAIL, SOUTH FRONT, PORTICO, COLUMN CAPITALS
DC-130-8 DETAIL, SOUTH FRONT, PORTICO, COLUMN CAPITAL AND CORNICE, WEST CORNER
DC-130-9 DETAIL, SOUTH FRONT, PILASTERS AND CORNICE (2 x 2 negative; 5 x 7 print)
DC-130-10 DETAIL, SOUTH FRONT, ENTRANCE DOOR (2 x 2 negative; 5 x 7 print)
DC-130-11 DETAIL, GROUND FLOOR, WINDOW (2 x 2 negative; 5 x 7 print)
DC-130-12 DETAIL, INTERIOR COURTYARD, WATER FOUNTAIN
DC-130-13 DETAIL, IRON STAIR RAILING, STREET LEVEL TO GROUND FLOOR LEVEL
(2 x 2 negative; 5 x 7 print)
DC-130-14 DETAIL, IRON STAIR RAILING, STREET LEVEL TO GROUND FLOOR LEVEL,
SHOWING NEWEL POST (2 x 2 negative; 5 x 7 print)
DC-130-15 DETAIL, IRON FENCE (2 x 2 negative; 5 x 7 print)
DC-130-16 INTERIOR, BASEMENT, GENERAL VIEW OF GARAGE
DC-130-17 INTERIOR, GENERAL VIEW OF SANDSTONE GALLERY
DC-130-18 INTERIOR, SANDSTONE GALLERY, DETAIL OF COLUMNS

- DC-130-19 INTERIOR, GRANITE GALLERY, GENERAL VIEW FROM THE NORTHEAST
- DC-130-20 INTERIOR, DOUBLE STAIRWAY LEADING TO MODEL HALL
- DC-130-21 INTERIOR, DOUBLE STAIRWAY LEADING TO MODEL HALL, DETAIL OF ONE FLIGHT (5 x 7 negative; 8 x 10 print)
- DC-130-22 INTERIOR, DOUBLE STAIRWAY LEADING TO MODEL HALL, DETAIL OF RAILING
- DC-130-23 INTERIOR, MODEL HALL, ENTRANCE AS SEEN FROM STAIR LANDING
- DC-130-24 INTERIOR, MODEL HALL, ENTRANCE AS SEEN FROM HALL INTERIOR
- DC-130-25 INTERIOR, MODEL HALL, LOOKING EAST
- DC-130-26 INTERIOR, MODEL HALL, WESTERN SECTION, LOOKING SOUTHWEST FROM BALCONY
- DC-130-27 INTERIOR, MODEL HALL, WESTERN SECTION, LOOKING WEST FROM BALCONY
- DC-130-28 INTERIOR, MODEL HALL, DETAIL OF FLOOR TILES
- DC-130-29 INTERIOR, MODEL HALL, DETAIL OF COLUMN CAPITAL
- DC-130-30 INTERIOR, MODEL HALL, DOOR, DETAIL OF ETCHED GLASS
- DC-130-31 INTERIOR, LINCOLN GALLERY, EAST WING LOOKING SOUTH
- DC-130-32 INTERIOR, THIRD FLOOR, LANDING, SOUTHEAST CORNER
- DC-130-33 Photocopy of photograph (from Library of Congress, #USZ62-24770)
() M'Clees, Photographer 1859
SOUTH PORTICO, WITH POST OFFICE IN FOREGROUND
(4 x 5 negative; 8 x 10 print)
- DC-130-34 Photocopy of photograph (from Library of Congress, #USZ6-166)
Kilburn Bros., Photographers 1889
SOUTH FRONT FROM THE SOUTHEAST
(4 x 5 negative, 8 x 10 print)
- DC-130-35 Photocopy of drawing (from Library of Congress)
Artist unknown 1891
SOUTH FRONT FROM THE SOUTHWEST
- DC-130-36 Photocopy of photograph
Standard Scenic Company, Photographers 1907
SOUTH FRONT LOOKING WEST
- DC-130-37 Photocopy of photograph (from Brady Handy Collection, Library of Congress, #BH 8234-48)
Photographer unknown, ca. 1910
SOUTH FRONT FROM THE WEST
(4 x 5 negative, 8 x 10 print)

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
DC,
WASH,
503-

ADDENDUM TO
PATENT OFFICE BUILDING
(U.S. CIVIL SERVICE COMMISSION)
(NATIONAL PORTRAIT GALLERY)
(NATIONAL MUSEUM OF AMERICAN ART)
Bounded by Seventh, Ninth, F and G Streets, NW
Washington
District of Columbia

HABS No. DC-130

DC-130-1 through DC-130-37 were transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, January 1986

DC-130-38 (CT)	SOUTH FRONT FROM THE SOUTHWEST
DC-130-39 (CT)	SOUTH FRONT FROM THE SOUTHEAST

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DC
WASH
503-

Addendum to
PATENT OFFICE BUILDING
(U.S. Civil Service Commission)
(National Portrait Gallery)
(National Museum of American Art)
Bounded by 7th, 9th, F & G Streets, NW
Washington
District of Columbia

HABS No. DC-130
(page 4)


Photographs HABS No. DC-130-1 through -37 and Color Transparencies HABS No. DC-130-38 to -39 were previously transmitted to the Library of Congress.


Bryan Becker, Photographer, November 2002


- DC-130-40 DETAIL, BASEMENT LEVEL, EAST MOAT FROM EAST STAIRS TO COURTYARD
- DC-130-41 INTERIOR, BASEMENT LEVEL, EAST MOAT ROOM FROM ENTRANCE
- DC-130-42 DETAIL, BASEMENT LEVEL, BRICK VAULTED DRAIN LINE AT EAST MOAT
- DC-130-43 DETAIL, BASEMENT LEVEL, EAST MOAT FROM NORTHEAST
- DC-130-44 DETAIL, BASEMENT LEVEL, NORTH MOAT FROM NORTHEAST
- DC-130-45 DETAIL, BASEMENT LEVEL, NORTH MOAT ROOM FROM ENTRANCE
- DC-130-46 INTERIOR, BASEMENT LEVEL, NORTH MOAT ROOM LOOKING EAST
- DC-130-47 INTERIOR, BASEMENT LEVEL, NORTH MOAT ROOM LOOKING WEST
- DC-130-48 DETAIL, BASEMENT LEVEL, NORTH MOAT FROM NORTHWEST
- DC-130-49 DETAIL, BASEMENT LEVEL, WEST MOAT AND STAIR TO COURTYARD
- DC-130-50 DETAIL, BASEMENT LEVEL, WEST MOAT FROM WEST STAIR TOWER
- DC-130-51 INTERIOR, BASEMENT LEVEL, WEST MOAT ROOM FROM ENTRANCE
- DC-130-52 INTERIOR, BASEMENT LEVEL, WEST MOAT ROOM LOOKING NORTH
- DC-130-53 INTERIOR, BASEMENT LEVEL, WEST MOAT ROOM LOOKING SOUTH
- DC-130-54 INTERIOR, BASEMENT LEVEL, WEST MOAT ROOM PENETRATION
- DC-130-55 DETAIL, BASEMENT LEVEL, WEST STAIR TOWER FROM WEST MOAT LOOKING NORTH
- DC-130-56 DETAIL, BASEMENT LEVEL, WEST MOAT FROM NORTHWEST


ADDENDUM TO:
PATENT OFFICE BUILDING
HABS No. DC-130
INDEX TO PHOTOGRAPHS
(page 5)

DC-130-57 INTERIOR, BASEMENT LEVEL, WEST STAIR TOWER, SOUTH WALL
DC-130-58 INTERIOR, BASEMENT LEVEL, WEST STAIR TOWER NORTH WALL
DC-130-59 INTERIOR, BASEMENT LEVEL, NORTH WING, WEST CEILING
DC-130-60 DETAIL, INTERIOR COURTYARD, WEST FOUNTAIN
DC-130-61 DETAIL, INTERIOR COURTYARD, WEST FOUNTAIN CAULDRON
DC-130-62 DETAIL, INTERIOR COURTYARD, CAST IRON POST AT NORTH BRIDGE
DC-130-63 AERIAL, INTERIOR COURTYARD FROM NORTHWEST ROOF
DC-130-64 AERIAL, INTERIOR COURTYARD FROM NORTHEAST ROOF
DC-130-65 AERIAL, INTERIOR COURTYARD FROM SOUTHEAST ROOF









HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:
PATENT OFFICE BUILDING
(U.S. Civil Service Commission)
(National Portrait Gallery)
(National Museum of American Art)
Bounded by Seventh, Ninth, F & G Streets, Northwest
Washington
District of Columbia

HABS DC-130

HABS
DC
WASH,
503-

Photos HABS DC-130-1 through HABS DC-130-65 have already been transmitted to Library of Congress.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Jack E. Boucher, photographer,

DC-130-66

General view