

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

St. Elizabeth's Hospital, "C" Building (#73)
2700 Martin Luther King, Jr. Avenue, S.E.
Washington
District of Columbia

HABS No. DC-349 B

Documentation: 7 exterior photos (1979)
2 interior photos (1979)

Photographed by Department of Health, Education and Welfare, June 1979

- DC-349 B-1 WEST (FRONT) FACADE
- DC-349 B-2 WEST FACADE, OBLIQUE VIEW
- DC-349 B-3 WEST AND SOUTH FACADES
- DC-349 B-4 NORTH FACADE FROM NORTHEAST
- DC-349 B-5 WEST FACADE DETAIL
- DC-349 B-6 WEST FACADE, DETAIL OF NORTH WING
- DC-349 B-7 DETAIL, FIRST FLOOR WINDOWS
- DC-349 B-8 INTERIOR, STAIRWAY
- DC-349 B-9 INTERIOR, ROOM IN WING

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO
C BUILDING (Building 73)
St. Elizabeths West Campus
Redwood Street SE
Washington, D.C.

HABS No. DC-349-B

Photographs DC-349-B-1 through DC-349-B-9 were transmitted previously to the Library of Congress.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Leslie Schwartz, photographer, January 2011.

- DC-349-B-10. West (front) facade, view from west
- DC-349-B-11. Partial north (side) and west facades, view from northwest
- DC-349-B-12. Partial south (side) and east (rear) facades, view from southeast
- DC-349-B-13. Partial east and north facades, view from northeast
- DC-349-B-14. Partial west facade, view from west
- DC-349-B-15. Partial west facade, view from west
- DC-349-B-16. Partial north and east facades, view from northeast
- DC-349-B-17. South sitting room, view from northeast
- DC-349-B-18. Dining room, view from west
- DC-349-B-19. Main staircase, view from southeast
- DC-349-B-20. Main staircase, view from southwest
- DC-349-B-21. Typical corridor, view from north
- DC-349-B-22. North porch, view from northwest