

# HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

SMITHSONIAN INSTITUTION, NATIONAL MUSEUM OF  
NATURAL HISTORY  
Tenth Street & Constitution Avenue, NW  
Washington  
District of Columbia

HABS DC-874


## INDEX TO BLACK AND WHITE PHOTOGRAPHS

Martin Stupich, photographer, April 2011

- |          |  |
|----------|--|
| DC-874-1 | General exterior oblique view, partial west side and north elevation; view to northeast  |
| DC-874-2 | Exterior view, detail of north elevation with dome, south pavilion main entrance, view is to northeast   |
| DC-874-3 | Detail, exterior roof, west side of dome with slate-clad roofs of west wing (left) and south pavilion (right); view is to north                                      |
| DC-874-4 | Detail, exterior, frieze and cornice, west side of dome; view is to east   |
| DC-874-5 | Exterior detail of dome, showing west side with access door, and connection to south pavilion slate-clad roof; view to east  |
| DC-874-6 | Interior general view of rotunda from third floor balcony; view is to east-southeast   |
| DC-874-7 | Interior view of rotunda first floor, south pavilion main entrance is far right; view is to southeast  |
| DC-874-8 | Interior view of rotunda, from main floor looking up to dome with oculus, showing east (left) and west (right) wing intersections with rotunda; view is up and south |
| DC-874-9 | Interior detail, typical column base, northeast corner of rotunda; view is to east-southeast   |

SMITHSONIAN INSTITUTION, NATIONAL MUSEUM OF  
HABS DC-874  
INDEX TO PHOTOGRAPHS  
Page 2

- DC-874-10 Interior general view of west wing from second floor balcony, view is to west
- DC-874-11 Interior detail, ceiling of west wing with lay light; view is to west
- DC-874-12 Interior view, east side of enclosed West Court with; view is to south
- DC-874-13 Interior general view of east wing from second floor balcony; view is to east
- DC-874-14 Interior view, south side of enclosed East Court, view is to west
- DC-874-15 Detail of stairway and ornamental banister, between first and second floors northeast corner of rotunda; view is to west
- DC-874-16 Detail of stairway and ornamental banister, northeast corner of south pavilion basement; view is to east
- DC-874-17 Interior general view of Baird Auditorium, toward stage, showing Gaustavino Vaulting; view is to southwest
- DC-874-18 Interior general view of Baird Auditorium, featuring Gaustavino Vaulting; view is from stage to north
- DC-874-19 Interior detail of Baird Auditorium ceiling with concealed illumination in Gaustavino Vaulting, encircled by terra cotta ornament; view is up and to west
- DC-874-20 Interior, between exterior and interior domes, showing masonry bracing, and stairless well leading to egress door (see HABS DC-874-3 and HABS DC-874-5 for exterior views of same area); view is to north
- DC-874-21 Interior, between exterior and interior domes, showing (late) metal stairs climbing interior dome, for access to oculus and sky light; view is to north
- DC-874-22 Interior, attic area with sky light and lay light (covered) over north wing; view is to south




National  
Museum  
of Natural  
History  
HABS DC-874

Exterior  
Photos

West Wing Roof







National  
Museum  
of Natural  
History  
HABS DC-874

Interior Photos  
(partial)






NMNH  
HABS DC-874  
BAIRD  
AUDITORIUM  
Photo Key



National  
Museum  
of Natural  
History  
HABS DC-874

Dome  
interior

West Wing



National  
Museum  
of Natural  
History  
HABS DC-874

Interior Photos  
(partial)

