

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

SMITHSONIAN INSTITUTION, FREER GALLERY OF ART
Jefferson Drive at 12th Street, SW
Washington
District of Columbia

HABS DC-875

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Martin Stupich, photographer, April 2011

- | | |
|----------|--|
| DC-875-1 | General exterior view of north elevation; view to southeast |
| DC-875-2 | Exterior view, main entrance portico, north side; view to southwest |
| DC-875-3 | Detail, north entrance cornice and frieze over central arch; view to south |
| DC-875-4 | Detail, main entrance, double doors, granite stairs to portico, hand rails; view is to south |
| DC-875-5 | Detail, main entrance, double doors (closed), hand rails; view is to south |
| DC-875-6 | Detail, north elevation, east side of central entry, showing niche set in granite wall. Barred basement window is typical; view to south-southeast |
| DC-875-7 | General view of building in setting southwest of Smithsonian Castle; view to southwest |
| DC-875-8 | East elevation, oblique from gardens south of the Smithsonian Castle; view to southwest |
| DC-875-9 | General Oblique view of south elevation, west end, articulating various details and surface treatments; view is to east-northeast |

SMITHSONIAN INSTITUTION, FREER GALLERY OF ART

HABS DC-875
INDEX TO PHOTOGRAPHS

Page 2

- DC-875-10 Detail, south elevation east of central entrance showing portico at top of granite stairs, light standard east of landing, double doors with ornamental lintel; view to north
- DC-875-11 Detail of southwest corner; photo articulates surface treatments and textures at grade level; view is to east-southeast
- DC-875-12 Detail, wider view of HABS DC-875-11 above, showing (left to right) west wall and south wall; view to northeast
- DC-875-13 General oblique view of northwest corner from parapet to grade; view from 12th Street SW to southeast
- DC-875-14 Exterior detail, central entry north side; view to northwest
- DC-875-15 General view, central courtyard with fountain; view to north
- DC-875-16 Detail of central courtyard fountain on axis of main north entrance visible through fenestrated archway; view to north
- DC-875-17 Courtyard detail of parapet, frieze, arches and pilasters at east cloister; view to northeast
- DC-875-18 Detail view inside east cloister showing pendant lamps at apexes of groin vaults; view to north
- DC-875-19 On roof, north section between parapet and skylight penthouse (note Smithsonian Castle tower in background left); left to east
- DC-875-20 On roof, west section skylights (note Old Post Office tower in background left); view to north
- DC-875-21 Interior general view of main (north) foyer with stair leading to north corridor; view to west-southwest
- DC-875-22 Interior detail, coffered ceiling of north foyer, seen from north corridor; view to northwest
- DC-875-23 Interior general view, north corridor from east of main entry along axis to west, with courtyard access to left, main north foyer to right; view is to west
- DC-875-24 Interior general view, Peacock Room, north wall; view to north

SMITHSONIAN INSTITUTION, FREER GALLERY OF ART

HABS DC-875
INDEX TO PHOTOGRAPHS

Page 3

- DC-875-25 Interior wide view of Peacock Room showing (left to right) east wall (with shutters open), south wall, and west wall; view to south
- DC-875-26 Interior wide view of Peacock Room showing ceiling panels with leaded ceiling light fixtures; view to southwest
- DC-875-27 Interior view of Gallery 8 (Religious Arts of Japan), showing skylights (lay lights, typical); view is to east
- DC-875-28 Interior detail, ornamental radiator grille, north corridor, north wall of east entrance; view to northwest
- DC-875-29 Interior detail, roof truss meeting north masonry wall (right); lay lights with sun-filtering fabric (bottom left) and roller shades in roof skylight (upper right); view to east