

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
DEL  
1-CAM,  
3-

Brecknock  
U.S. Route 13  
Camden  
Kent County  
Delaware

DE-178

Documentation: 10 exterior photos (1982)  
12 interior photos (1982)  
12 data pages (1975)  
1 set of field records (National Register nomination)

Jack. E. Boucher, Photographer July, 1982

DE-178-1 SOUTHEAST FRONT

DE-178-2 SOUTHEAST FRONT AND NORTHEAST SIDE

DE-178-3 SOUTHEAST FRONT AND NORTHEAST SIDE, CLOSER

DE-178-4 NORTHEAST SIDE, FROM NORTH

DE-178-5 NORTHEAST AND NORTHWEST SIDES OF ORIGINAL BRICK SECTION

DE-178-6 NORTHWEST SIDE OF ORIGINAL SECTION, DETAIL OF BELT COURSE

DE-178-7 NORTHWEST AND SOUTHWEST SIDES

DE-178-8 SOUTHWEST SIDE

DE-178-9 SOUTHWEST SIDE AND SOUTHEAST FRONT

DE-178-10 SOUTHEAST FRONT, FROM SOUTH

DE-178-11 SOUTH ROOM, LOOKING SOUTHWEST

DE-178-12 SOUTH ROOM, WEST CORNER, DETAIL OF CUPBOARD

DE-178-13 CENTER STAIRWAY, DETAIL OF NEWEL POST AND BALUSTRADE

DE-178-14 CENTER STAIRWAY, DETAIL OF BALUSTRADE

DE-178-15 DINING ROOM (EAST ROOM) DOOR, DETAIL OF THUMB LATCH

DE-178-16 DINING ROOM (EAST ROOM), OTHER SIDE, DETAIL OF BOX LOCK

DE-178-17 NORTH ROOM (ORIGINAL BRICK SECTION), LOOKING NORTHWEST

DE-178-18 ATTIC OVER NORTH SECTION, LOOKING NORTHWEST

DE-178-19 ATTIC OVER NORTH SECTION, DETAIL OF DOOR

DE-178-20 ATTIC OVER NORTH SECTION, DETAIL OF LEATHER HINGES ON DOOR

DE-178-21 ORIGINAL BRICK INSCRIBED "CARVEL MOULDE"

DE-178-22 ORIGINAL BRICK INSCRIBED "CARVEL MOULDE", WITH SCALE

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:  
BRECKNOCK  
U.S. Route 13  
Camden Vicinity  
Kent County  
Delaware

HABS No. DE-178 1-CAM,

HABS  
DEL,  
3-

DE-178-1 through DE-178-22 were transmitted to the Library of Congress in 1983.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, May 1982

DE-178-23 (CT) SOUTHEAST FRONT AND NORTHEAST SIDE

DE-178-24 (CT) NORTHEAST SIDE FROM THE NORTH