

503 SOUTH JACKSON STREET (HOUSE)
503 South Jackson Street
Albany
Dougherty County
Georgia

HABS GA-1175-F
GA-1175-F

HABS
GA-1175-F

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
SOUTHEAST REGIONAL OFFICE
National Park Service
U.S. Department of the Interior
100 Alabama St. NW
Atlanta, GA 30303

STATE Georgia		COUNTY Dougherty	TOWN OR VICINITY Albany
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Sam Farkas Estate (Tax Records)			HABS NO. GA-1175-F
SECONDARY OR COMMON NAMES OF STRUCTURE Not Applicable			
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 503 South Jackson Street, Albany, Georgia			
DATE OF CONSTRUCTION (INCLUDE SOURCE) Tax Records and Underwriters 1920+ Map Association 1919, Map No. 52		ARCHITECT(S) (INCLUDE SOURCE) Unknown	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Significant for its association with the development of the black residential community in Albany, Georgia. Building is included within an intact row of early 20th century residences in this part of the city and contains an example of a vernacular house form typical of black housing of that era.			
STYLE (IF APPROPRIATE) Early 20th Century Vernacular - single "shotgun".			
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Light wood frame structure with pine floors and metal shingle, gable-styled roof.			
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGE ARE ACCEPTABLE) Rectangular shape; 16' x 37'; 1 story. (see attached sketches)			
EXTERIOR FEATURES OF NOTE Recessed front porch is supported by plain posts; plain door and window framing; windows are six over six; central interior brick chimney and recessed back porch in northwest corner.			
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Consists of three rooms (see attached sketches), with pine floors and wood interior walls.			
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Part of back porch at northwest corner of structure was enclosed and converted into a partial bathroom, however no date or building permit could be located.			
PRESENT CONDITION AND USE Poor, severely dilapidated. This vacant building, formerly residential has been condemned by Inspection Department.			
OTHER INFORMATION AS APPROPRIATE Documentation for this structure was prepared by Albany Metropolitan Planning Commission and Thronateeska Heritage Foundation, Albany, Ga., in compliance with Executive Order 11592 and a Memorandum of Agreement with the Advisory Council on Historic Preservation.			
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Property Record Cards, Dougherty County Tax Department; determined eligible for National Register of Historic Places.			
COMPILER, AFFILIATION Eric Montgomery, Director Thronateeska Heritage Foundation Albany, Georgia			DATE 5-20-82
			Mary A. Teter Albany Metro Planning Comm. Albany, Georgia

