

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
ID
8-PLAVI.V
IA-

Hiatt Property, House HABS No. ID-117-A
West Bank of Woof Creek, 400 feet northwest
of the intersection of USFS Roads #651 and #349
Placerville Vicinity
Boise County
Idaho

John Baker, Photographer

April 1996

- ID-117-A-1 VIEW OF SOUTH FRONT OF HIATT-STRICKLIN HOUSE SHOWING FRONT PORCH, MODERN STAIRS AND SOUTH PORCH ENTRY ALTERATION, FACING NORTH.
- ID-117-A-2 VIEW OF WEST SIDE OF HIATT-STRICKLIN HOUSE SHOWING FRONT PORCH, ALUMINUM SIDING TO COVER FOUNDATION DAMAGE AND SHUTTERS.
- ID-117-A-3 VIEW OF SOUTH SIDE OF HIATT-STRICKLIN HOUSE SHOWING ADDITION AND ROCK WALL, FACING NORTH.
- ID-117-A-4 VIEW OF HIATT-STRICKLIN HOUSE SHOWING WEST GABLE END OF ADDITION. NOTE LARGE DOOR ON THE RIGHT, FACING SOUTHEAST.
- ID-117-A-5 VIEW OF HIATT-STRICKLIN HOUSE SHOWING NORTH GABLE END AND NORTH SIDE OF ADDITION. NOTE THE COVERED PORCH, FACING SOUTH.
- ID-117-A-6 VIEW OF HIATT-STRICKLIN HOUSE SHOWING NORTH GABLE BACK AND EAST SIDE. NOTE THE PORCHES, SHUTTERS AND CHIMNEY. THE SHINY SQUARES ON THE SIDING ARE METAL PIECES TO REPAIR WOODPECKER HOLES, FACING SOUTHWEST.
- ID-117-A-7 VIEW OF HIATT-STRICKLIN HOUSE SHOWING SOUTH GABLE FRONT AND EAST SIDE. NOTE DAMAGE ALONG SILL AND ABOVE NORTH PORCH, FACING NORTHWEST.
- ID-117-A-8 VIEW OF HIATT-STRICKLIN HOUSE SHOWING THE EAST SIDE, NORTH GABLE BACK, AND NORTH SIDE OF ADDITION, FACING SOUTHWEST.

HIATT PROPERTY (Stricklin Property)
HABS No. ID-117-A
INDEX TO PHOTOGRAPHS (page 2)

- ID-117-A-9 VIEW OF HIATT-STRICKLIN HOUSE SHOWING WEST GABLE END AND NORTH SIDE OF ADDITION, FACING SOUTHEAST.
- ID-117-A-10 VIEW OF HIATT-STRICKLIN HOUSE INTERIOR SHOWING FRONT OFFICE DOOR. NOTE THE FOUR PANEL DOOR, TRIM, WALL PAPER AND LINOLEUM, FACING SOUTHWEST.
- ID-117-A-11 VIEW OF HIATT-STRICKLIN HOUSE INTERIOR SHOWING KITCHEN CUPBOARD, SINK, AND SHELVES, FACING NORTHEAST.
- ID-117-A-12 VIEW OF HIATT-STRICKLIN HOUSE INTERIOR SHOWING KITCHEN, ENTRY AND STAIRCASE. NOTE CUPBOARD AND WOOD BOX, FACING NORTHWEST.
- ID-117-A-13 VIEW OF HIATT-STRICKLIN HOUSE INTERIOR STANDING IN PARLOR LOOKING THROUGH THE DINING ROOM INTO THE THE NORTHEAST BEDROOM, FACING NORTHEAST.
- ID-117-A-14 VIEW OF HIATT-STRICKLIN HOUSE INTERIOR SHOWING UPSTAIRS STAIRCASE, LANDING AND BEDROOM, FACING NORTHWEST.