

HISTORIC AMERICAN BUILDING SURVEY

INDEX TO PHOTOGRAPHS

ANDERSON ELECTRIC COMPANY

293 A Street
Boston, ~~Middlesex~~ ^{Suffolk} County
Massachusetts

HABS
MASS
13-BOST
142-
HABS No. MA-1273

Photographer: (Views 1-30) Martin Stupich Dec. 1993-Feb. 1994

- MA-1273-1 VIEW SOUTHEAST, NORTH WALL
- MA-1273-2 VIEW SOUTHEAST, NORTH WALL
- MA-1273-3 VIEW SOUTHEAST, WEST WALL
- MA-1273-4 VIEW NORTHEAST, WEST AND SOUTH WALLS
- MA-1273-5 Center building
VIEW NORTH, SOUTH AND EAST WALLS
- MA-1273-6 VIEW NORTHWEST, SOUTH AND EAST WALLS
- MA-1273-7 VIEW NORTHWEST, SOUTH AND EAST WALLS
- MA-1273-8 First floor facade details
VIEW NORTHEAST, WEST WALL
- MA-1273-9 Center entrance
VIEW NORTHEAST, WEST WALL
- MA-1273-10 Detail of lion brackets, center entrance
VIEW NORTHEAST, WEST WALL
- MA-1273-11 Detail of loading bay and north entrance
VIEW NORTHEAST, WEST WALL
- MA-1273-12 Detail of cornice and elevator penthouse
VIEW NORTHEAST, WEST WALL
- MA-1273-13 Interior view of granite block foundation, basement
VIEW NORTHWEST, NORTH WALL
- MA-1273-14 Interior view of timber framing, joists and beams, third floor
- MA-1273-15 Interior view of cast iron straps with iron staples joining column and beam,
third floor

- MA-1273-16 Interior view of intersection of brick wall, timber sill and framing
VIEW NORTHEAST, EAST WALL
- MA-1273-17 Interior view of chimney flue and original window
VIEW SOUTHEAST, EAST WALL
- MA-1273-18 Interior view of arched windows in facade, fifth floor
VIEW WEST, WEST WALL
- MA-1273-19 Interior view of north staircase and entrance doors
VIEW SOUTHWEST
- MA-1273-20 Interior view of north staircase newel posts, bannister and dropped pendant
detail
VIEW SOUTHWEST
- MA-1273-21 Interior view of south staircase, detail of metal newel post and metal paneled
stairs, first floor landing
VIEW NORTHEAST
- MA-1273-22 Interior view of typical cutting and sewing floor, fifth floor
VIEW NORTH
- MA-1273-23 View of safe, first floor
VIEW SOUTHWEST
- MA-1273-24 Original door, on facade
VIEW EAST