

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MD,
3-OWMI.V
3-A-

Blendon Estate, Tenant House
11747 Park Heights Avenue
Owings Mills Vicinity
Baltimore County
Maryland

HABS No. MD- 994-A

Photographer: (All views) Martin Stupich

November 1989


- MD- 994-A-1 SOUTH ELEVATION OF TENANT HOUSE, VIEW TO NORTH
- MD- 994-A-2 OBLIQUE VIEW OF TENANT HOUSE SOUTHEAST CORNER, VIEW TO NORTHWEST
- MD- 994-A-3 EAST ELEVATION OF TENANT HOUSE, VIEW TO WEST
- MD- 994-A-4 OBLIQUE REAR VIEW OF TENANT HOUSE, VIEW TO SOUTHWEST
- MD- 994-A-5 OBLIQUE REAR VIEW OF TENANT HOUSE, VIEW TO SOUTH/SOUTHWEST
- MD- 994-A-6 OBLIQUE FRONT VIEW OF TENANT HOUSE, VIEW TO NORTHEAST
- MD- 994-A-7 STAIRS IN MAIN BACK (NORTH) ROOM, VIEW TO SOUTH, CUPBOARD DOOR CLOSED
- MD- 994-A-8 SAME VIEW, CUPBOARD DOOR OPEN
- MD- 994-A-9 UPPER SOUTH ROOM, NORTHWEST CORNER, WITH STAIRWELL
- MD- 994-A-10 UPPER ROOMS, VIEW THROUGH CENTER HALL FROM NORTH ROOM TOWARD SOUTH ROOM
- MD- 994-A-11 CELLAR, VIEW TO SOUTHWEST WITH STAIRS

INDEX TO PHOTOGRAPHS
BLENDON ESTATE,
TENANT HOUSE
HABS NO. MD-994-A (PAGE 2)

EXTERIOR VIEWS

A-5 ↙

↘ A-4




← A-3

↖ A-6


↑ A-1

↙ A-2


INTERIOR VIEWS




Second Floor



First Floor



Basement



NOT TO SCALE

KEY TO PHOTOGRAPHS TENANT HOUSE INTERIORS AND EXTERIORS

December 1989