

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MD
1-FLINT.V
1-

William House Farm
East side of West Wilson Road,
approximately 0.7 mile north of Breakneck Road
Flintstone vicinity
Allegany County
Maryland

HABS No. MD-1081

Photographer: (all views) J. Brough Schamp November 3, 1993

- MD- 1081 -1 GENERAL VIEW FROM SOUTHEAST, SHOWING COMPLEX
IN SETTING: BARN IN RIGHT FOREGROUND, STORAGE
SHED IN LEFT FOREGROUND, DWELLING AND
OUTBUILDINGS IN DISTANCE
- MD- 1081 -2 GENERAL VIEW FROM NORTHEAST, SHOWING COMPLEX
IN SETTING: BARN IN FOREGROUND, DWELLING AND
OUTBUILDINGS IN DISTANCE
- MD-1081 -3 VIEW OF DWELLING FROM SOUTH
- MD- 1081 -4 WASH HOUSE, WEST GABLE AND SOUTH SIDE, VIEW
FROM SOUTHWEST
- MD- 1081 -5 OUTBUILDINGS, VIEW FROM NORTHWEST, SHOWING
(RIGHT TO LEFT) WASH HOUSE, POULTRY SHED,
[COLLAPSED] PRIVY, AND ANIMAL SHED
- MD- 1081 -6 OUTBUILDINGS, VIEW FROM SOUTHEAST, SHOWING
(LEFT TO RIGHT) WASH HOUSE, POULTRY SHED,
[COLLAPSED] PRIVY, AND ANIMAL SHED
- MD- 1081 -7 VIEW FROM NORTHEAST, SHOWING RELATIONSHIP OF
OUTBUILDINGS TO DWELLING; NORTH SIDES OF
POULTRY SHED AND WASH HOUSE AT LEFT, DWELLING
IN DISTANCE

