

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
MONT  
47-MEL.V  
IT-

William and Lucina Bowe Ranch,  
Log Calving Barn  
230 feet south-southwest of House  
Melrose Vicinity  
Silver Bow County  
Montana

HABS No. MT-104-T

Documentation: 5 exterior photographs (1997)  
1 interior photograph (1997)  
2 data pages

Kristi Hager, Photographer, June 1997

- MT-104-T-1 LOG CALVING BARN. NORTH SIDE. VIEW TO SOUTH.
- MT-104-T-2 LOG CALVING BARN. EAST SIDE. VIEW TO WEST.
- MT-104-T-3 LOG CALVING BARN. SOUTH SIDE. VIEW TO NORTH.
- MT-104-T-4 LOG CALVING BARN. WEST SIDE. VIEW TO EAST.
- MT-104-T-5 LOG CALVING BARN. DETAIL OF WALL CORNER SHOWING HALF DOVETAIL NOTCHING ON HAND-HEWN LOGS.
- MT-104-T-6 LOG CALVING BARN. INTERIOR VIEW SHOWING LOG POST-AND-BEAM SUPPORT SYSTEM AND ANIMAL STALLS.