

PISGAH NATIONAL FOREST INN, WORKSHOP-GARAGE
Blue Ridge Parkway Milepost 408.6
Ashville
Buncombe County
North Carolina

HABS No. NC-356-B

HABS
NC-356-B


PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Southeast Region
Atlanta, Georgia 30303

ARCHITECTURAL DATA FORM

STATE North Carolina	COUNTY Buncombe	TOWN OR VICINITY Ashville
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Workshop/garage (name derives from historic usage)		HABS NO. NC 356-B
SECONDARY OR COMMON NAMES OF STRUCTURE Garage and shop		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) Parkway Inn, Inc., P. O. Box 749, Waynesville, NC 28706 (This structure is part of the Old Pisgah Inn complex located at Parkway milepost 408.6 on Parkway left, three miles south of NC 151).		
DATE OF CONSTRUCTION (INCLUDE SOURCE) 1919-20 according to Old Pisgah Inn National Register Nomination Form	ARCHITECT(S) (INCLUDE SOURCE) George F. Weston according to Carl A. Schenck, <u>The Biltmore Story</u>	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The workshop/garage is the larger of the two rectangular outbuildings. It has served as a basic support structure for operations at the Old Pisgah complex.		
STYLE (IF APPROPRIATE) Derived from William West Durant's Adirondack architecture known as the "Pine Knot Style."		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) The workshop/garage is covered with board and batten siding.		
TYPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) The workshop/garage is rectangular, about 36½ ft. by 21½ ft.		
EXTERIOR FEATURES OF NOTE Board and batten siding is water stained and rotted near the foundation sill. The garage entrance is open, covered by 2 large wire gates.		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Workshop/garage is approximately 1/3 workshop, 2/3 garage, separated by a wooden wall.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES An open storage lean-to, wire sides and fiberglass roof, was added to the side of the garage in 1984-85.		
PRESENT CONDITION AND USE As noted the exterior suffers long term water damage. The interior is an actively used maintenance and support facility. It shows the deterioration of years of hard use.		
OTHER INFORMATION AS APPROPRIATE None.		
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) National Register Of Historic Places Inventory, Nomination Form - 10/14/82 completed by a consultant to the North Carolina Division of Archives and History, updated and amplified 3/26/86 by NPS, SERO.		
COMPILER, AFFILIATION Allen R. Hess, Cultural Resource Management Specialist, BRP	DATE 4/29/88	



BUILDING NO. 564
GARAGE AND SHOP
HABS SKETCH DRAWING
NOVEMBER 25, 1987
BLUE RIDGE PARKWAY

1 in. = 5 ft.

782 sq. FT.