

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
OHIO
40-JACK,
1-

THE CAMBRIAN
(Cambrian Hotel)
254 East Main Street
Jackson
Jackson County
Ohio

HABS No. OH-2133

- OH-2133-1 West exterior elevation.
- OH-2133-2 East exterior elevation, full view at alley.
- OH-2133-3 East exterior elevation, focusing on hotel structure.
- OH-2133-4 South exterior elevation.
- OH-2133-5 West exterior elevation.
- OH-2133-6 North exterior elevation, west segment.
- OH-2133-7 North exterior elevation, east segment.
- OH-2133-8 West exterior elevation, detail of building face center section.
- OH-2133-9 West exterior elevation, detail of north-west corner window bay and roof cupola.
- OH-2133-10 View of First Floor Hotel Lobby, from front to rear (west to east).
- OH-2133-11 View of First Floor Hotel Lobby, from rear to front (east to west).
- OH-2133-12 View of ceramic tile hotel crest, in north-west corner of floor, First Floor Hotel Lobby; to be removed intact and relocated.
- OH-2133-13 View of best remaining ceramic tile floor pattern, First Floor Hotel Lobby; majority of remaining ceramic tile floor destroyed or damaged beyond repair.

(continued)

THE CAMBRIAN
(Cambrian Hotel)
HABS No. OH-2133
INDEX TO PHOTOGRAPHS
(Page 2)

- OH-2133-14 View from First Floor Hotel Lobby to secondary lobby area, with small Retail Area and original Barber Shop area beyond.
- OH-2133-15 View of best remaining ceiling cornice detail, First Floor Hotel Lobby; majority of original has been destroyed.
- OH-2133-16 View from balcony door to rear (west to east) of Second Floor Dining Room.
- OH-2133-17 View from rear to front (east to west) of Second Floor Dining Room.
- OH-2133-18 View of wall pilaster and ceiling cornice detail, Second Floor Dining Room.
- OH-2133-19 View of Service Area and Rear Stairwell at back of Second Floor Dining Room.
- OH-2133-20 View of center Corridor (east to west) serving Hotel Guest Rooms, typical of Third and Fourth Floors.
- OH-2133-21 View of Hotel Guest Room, typical at Third and Fourth Floors.
- OH-2133-22 View of north-west corner window bay, Third Floor.
- OH-2133-23 View through Hotel Guest Room to south window bay, with partial view of Bathroom, Third Floor.
- OH-2133-24 View of Fifth Floor Corridor, east to west.
- OH-2133-25 View of Fifth Floor Apartment, from Bedroom, through Living-Dining Room, and to Kitchen area.
- OH-2133-26 View to east of collapsed building section, Third Floor.
- OH-2133-27 View to west of collapsed building section, Third Floor.
- OH-2133-28 View full-length of Basement in 2-Story Retail (Furniture) Building, looking east; this is not a character-defining space.

(continued)

THE CAMBRIAN
(Cambrian Hotel)
HABS No. OH-2133
INDEX TO PHOTOGRAPHS
(Page 3)

- OH-2133-29 View from front to rear (west to east) on First Floor of 2-Story Retail (Furniture) Building.
- OH-2133-30 View from rear to front (east to west) on First Floor of 2-Story Retail (Furniture) Building.
- OH-2133-31 View from rear to front (east to west) on Second Floor of 2-Story Retail (Furniture) Building.