

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS NO. PA-6050-A

HABS
PA
46-AMB,
11A-

LINDENWOLD, CASTLE
(St. Mary's Villa)
701 Bethlehem Pike
Ambler
Montgomery County
Pennsylvania

James Scott, photographer, June/July 1994

- PA-6050-A-1 ENVIRONMENTAL VIEW TAKEN FROM THE WEST
- PA-6050-A-2 PERSPECTIVE VIEW OF CASTLE WITH ORNATE CONCRETE
PLANTER IN FOREGROUND FROM SOUTHWEST
- PA-6050-A-3 ELEVATION VIEW OF FRONT FACADE OF CASTLE TAKEN FROM
THE WEST WITHOUT SCALE
- PA-6050-A-4 ELEVATION VIEW OF FRONT FACADE OF CASTLE TAKEN FROM
THE WEST WITH SCALE
- PA-6050-A-5 ELEVATION VIEW OF WEST FACADE
- PA-6050-A-6 PERSPECTIVE VIEW FROM SOUTHWEST
- PA-6050-A-7 PERSPECTIVE VIEW FROM SOUTHWEST - VERTICAL
- PA-6050-A-8 VIEW OF TOWER TAKEN FROM NORTH WITHOUT SCALE
- PA-6050-A-9 VIEW OF TOWER TAKEN FROM NORTH WITH SCALE
- PA-6050-A-10 SIDE VIEW OF CASTLE AND ENTRANCE DOOR TAKEN FROM
THE NORTHEAST
- PA-6050-A-11 VIEW OF FOUNTAIN ON EAST WALL
- INTERIOR:
- PA-6050-A-12 OVERALL VIEW OF RECEPTION ROOM TAKEN WITH DOORS TO
THE ROOM PARTLY OPENED, FROM THE NORTH
- PA-6050-A-13 OVERALL OF RECEPTION ROOM TAKEN FROM THE NORTH
- PA-6050-A-14 CLOSEUP VIEW OF FIREPLACE IN RECEPTION ROOM TAKEN
FROM THE NORTH
- PA-6050-A-15 VIEW OF THE STAIRCASE IN THE MAIN ENTRANCE HALL
TAKEN FROM THE SOUTHWEST
- PA-6050-A-16 DETAIL OF WOOD CARVING OF CHERUBS ON WALL OF

STAIRWAY IN MAIN ENTRANCE HALL

- PA-6050-A-17 DETAIL OF WOOD CARVING ON MOLDING IN THE MAIN
ENTRANCE HALL, TAKEN FROM THE WEST
- PA-6050-A-18 OVERALL VIEW OF LIBRARY ON FIRST FLOOR TAKEN FROM
THE SOUTH
- PA-6050-A-19 CLOSEUP OF FIREPLACE IN LIBRARY ON THE FIRST FLOOR
- PA-6050-A-20 CLOSEUP OF WALL SCONCE ON NORTH WALL OF LIBRARY ON
FIRST FLOOR
- PA-6050-A-21 CLOSEUP OF FIGUREHEAD CARVED ON FIREPLACE IN THE
EAST WALL OF THE LIBRARY ON THE FIRST FLOOR
- PA-6050-A-22 CLOSEUP OF THE FIREPLACE IN SR. EVANGELINE'S OFFICE
TAKEN FROM THE NORTHWEST