

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPH

HABS  
SC,  
10-CHAR,  
124-

Addendum to:

Governor Thomas Bennett House  
1 Lucas Street  
Charleston County  
South Carolina

HABS No. SC-101

Documentation: 2 exterior photos (1940)  
1 photocopy of floor plan (1940)  
1 data page (1941)

SC-101-3 Photocopy of floor plan, from a sketch in the 1940 HABS  
index card

HABS  
SC  
10-CHAR  
124-

page 2

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to:

Governor Thomas Bennett House  
1 Lucas Street  
Charleston  
Charleston County  
South Carolina

HABS No. SC-101

Photos SC-101-1 thru SC-101-3 were previously transmitted to the Library of Congress.

The photos below were taken for the 1977-79 South Carolina project made possible by grants from the National Endowment for the Arts. Charles N. Bayless, AIA, was the photographer.

PHOTO DATES: 1977-78

- SC-101-4        GENERAL VIEW FROM SOUTHEAST (the porch faces south)
- SC-101-5        GENERAL VIEW, FROM SOUTHWEST
- SC-101-6        REAR VIEW OF HOUSE, SHOWING NORTH (left) AND WEST SIDES
- SC-101-7        EAST SIDE, WITH ENTRY AT SOUTHEAST CORNER
- SC-101-8        EAST SIDE AND NORTH REAR
- SC-101-9        ENTRY, LOCATED AT SOUTHEAST CORNER OF EAST SIDE
- SC-101-10       DETAIL OF EAST ENTRY STAIRS (southeast corner of east side)
- SC-101-11       SOUTH SIDE ENTRY, FIRST FLOOR PORCH
- SC-101-12       SOUTH PEDIMENT AND WINDOW DETAIL
- SC-101-13       EAST PEDIMENT AND WINDOW DETAIL
- SC-101-14       FIRST FLOOR HALL, LOOKING SOUTHEAST. The door leads to the south porch (see Photo SC-101-11).
- SC-101-15       FIRST FLOOR HALL, LOOKING NORTH (entered from south entry door). Glazed arch partition taken from second floor center hall room (see Photo SC-101-32)

(continued on page 2)

GOV. THOMAS BENNETT HOUSE  
Index To Photographs  
HABS No. SC-101 (page 2)  
3

- SC-101-16 FIRST FLOOR HALL LOOKING SOUTH FROM STAIR, TOWARDS SOUTH ENTRY DOOR
- SC-101-17 FIRST FLOOR HALL: CEILING CENTERPIECE AND CORNICE DETAIL
- SC-101-18 FIRST FLOOR HALL: INTERESTING DETAILS UNDER SECOND FLOOR LANDING (west wall of hall)
- SC-101-19 FIRST FLOOR HALL: DOOR TO SOUTHEAST ROOM
- SC-101-20 STAIRWELL, AS SEEN FROM THE FIRST FLOOR HALL
- SC-101-21 FIRST FLOOR, SOUTHEAST ROOM, LOOKING NORTHEAST
- SC-101-22 FIRST FLOOR, SOUTHEAST ROOM, LOOKING NORTHWEST
- SC-101-23 FIRST FLOOR, SOUTHEAST ROOM: MANTLE DETAIL
- SC-101-24 FIRST FLOOR, SOUTHEAST ROOM: CEILING CENTERPIECE
- SC-101-25 FIRST FLOOR, SOUTHEAST ROOM: CORNICE DETAIL
- SC-101-26 FIRST FLOOR, SOUTHWEST ROOM, LOOKING NORTHWEST
- SC-101-27 FIRST FLOOR, SOUTHWEST ROOM, NORTH WALL
- SC-101-28 FIRST FLOOR, SOUTHWEST ROOM: CEILING CENTERPIECE
- SC-101-29 FIRST FLOOR, SOUTHWEST ROOM, NORTH WALL: MANTLE DETAIL
- SC-101-30 SECOND FLOOR STAIRHALL: WINDOW DETAIL
- SC-101-31 SECOND FLOOR: FILLED-IN CENTER HALL WITH PARTITION UNDER ARCH, LOOKING NORTH. ALSO NOTE CEILING CENTERPIECE
- SC-101-32 SECOND FLOOR CENTER HALL ROOM: GLAZED ARCH PARTITION TAKEN FROM UNDER THIS DIVIDING ARCH AND INSTALLED IN FIRST FLOOR HALL (see Photo SC-101-15).
- SC-101-33 SECOND FLOOR, SOUTHEAST ROOM, NORTH WALL. Ceiling centerpiece original to this room now destroyed
- SC-101-34 SECOND FLOOR, SOUTHEAST ROOM: WINDOW ARCHITRAVE AND ROOM CORNICE
- SC-101-35 SECOND FLOOR, SOUTHEAST ROOM, NORTH WALL: BLACK MARBLE MANTLE. Grape clusters above columns repeat in upper part of cornice and probably in destroyed ceiling centerpiece