

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ELLSWORTH AIR FORCE BASE,
GROUP ADMINISTRATION & SECURE STORAGE BUILDING
(Building No. 7810)
2372 Westover Avenue
Black Hawk Vicinity
Meade County
South Dakota

HABS No. SD-21-W

Bill Groethe, Photographer, October, 1997

Note: 4" x 5" images were made from 4" x 5" negatives.

- SD-21-W-1 SOUTH FRONT; VIEW TO NORTH.
- SD-21-W-2 SOUTHEAST CORNER; VIEW TO NORTHWEST.
- SD-21-W-3 EAST SIDE; VIEW TO WEST.
- SD-21-W-4 NORTHEAST CORNER; VIEW TO SOUTHWEST.
- SD-21-W-5 NORTH BACK; VIEW TO SOUTH.
- SD-21-W-6 NORTHWEST CORNER; VIEW TO SOUTHEAST.
- SD-21-W-7 WEST SIDE; VIEW TO EAST.
- SD-21-W-8 INTERIOR VIEW OF UNOCCUPIED OFFICE SPACE; SHOWING EXTERIOR WINDOWS, EXTERIOR DOOR AT FAR LEFT, AND OPENED DOORWAY TO CORRIDOR; NORTH END OF EAST WING ON TOP FLOOR; VIEW TO SOUTHEAST.
- SD-21-W-9 INTERIOR VIEW OF UNOCCUPIED OFFICE; SHOWING EXTERIOR WINDOWS AND CLOSET AT FAR END OF ROOM; SOUTHWEST CORNER OF EAST WING ON TOP FLOOR; VIEW TO NORTHWEST.
- SD-21-W-10 INTERIOR VIEW OF LARGE UNOCCUPIED OFFICE SPACE; SHOWING EXTERIOR WINDOWS; NEAR NORTHEAST CORNER OF MAIN SECTION OF BUILDING ON TOP FLOOR; VIEW TO NORTHEAST.
- SD-21-W-11 INTERIOR VIEW OF OFFICE SPACE LOOKING AT OPENED DOORWAY TO CORRIDOR; NEAR CENTER AND SOUTH SIDE OF MAIN SECTION OF BUILDING ON TOP FLOOR; VIEW TO SOUTHWEST.

- SD-21-W-12 INTERIOR VIEW OF RECEPTION AND SECRETARIAL SPACE FOR LEGAL OFFICES; SHOWING WALL MOUNTED SHELVING AND EXTERIOR WINDOW; CENTER AND SOUTH SIDE OF MAIN SECTION OF BUILDING ON TOP FLOOR; VIEW TO SOUTHWEST.
- SD-21-W-13 INTERIOR VIEW OF OFFICE SPACE WITH MULTIPLE STATIONS; SHOWING EXTERIOR WINDOWS AND OPENED DOORWAY TO PRIVATE OFFICE; TOWARDS WEST END AND NORTH SIDE OF MAIN SECTION OF BUILDING ON TOP FLOOR; VIEW TO NORTHEAST.
- SD-21-W-14 INTERIOR VIEW OF MEN'S RESTROOM LOOKING TOWARDS SUPPLIES CLOSET AT FAR END OF RESTROOM, SHOWING LAVATORY AREA WITH FULL MIRROR, OPENED SUPPLIES CLOSET, URINAL AND TOILET PARTITIONS; NEAR NORTHWEST CORNER OF MAIN SECTION OF BUILDING ON TOP FLOOR; VIEW TO NORTHWEST.
- SD-21-W-15 INTERIOR VIEW OF PRIVATE OFFICE; SHOWING BUILT IN BOOKCASE, CLOSET, AND EXTERIOR WINDOWS; SOUTHWEST CORNER OF MAIN SECTION OF BUILDING ON TOP FLOOR; VIEW TO NORTHWEST.
- SD-21-W-16 INTERIOR VIEW OF ENCLOSED STAIRWAY LOOKING AT OPENED DOORWAY TO TOP FLOOR CORRIDOR; SOUTHEAST CORNER OF WEST WING BETWEEN TOP AND MAIN FLOOR; VIEW TO WEST.
- SD-21-W-17 INTERIOR VIEW OF COURTROOM LOOKING TOWARDS JUDGE'S BENCH; SHOWING BUILT IN LINEAR SEATING ON BOTH ENDS OF ROOM, CLERICAL DESK AND EQUIPMENT, THROUGH WALL AIR CONDITIONING UNITS, EXTERIOR WINDOWS AND DOOR; NORTH END OF WEST WING ON TOP FLOOR; VIEW TO NORTHWEST.
- SD-21-W-18 INTERIOR VIEW OF LARGE UNOCCUPIED MEETING/GATHERING ROOM LOOKING TOWARDS SMALL STAGE AND OPENED DOORWAY TO EXTERIOR VESTIBULE; SHOWING THROUGH WALL AIR CONDITIONING UNIT; NORTH END OF EAST WING ON MAIN FLOOR; VIEW TO SOUTHWEST.
- SD-21-W-19 INTERIOR VIEW OF LARGE UNOCCUPIED OFFICE SPACE LOOKING TOWARDS OPENED DOORWAY TO CORRIDOR; SHOWING INTERIOR AND EXTERIOR WINDOWS, AND SEPARATED OFFICE SPACE; MAIN PORTION OF EAST WING ON MAIN FLOOR; VIEW TO SOUTH.


- SD-21-W-20 INTERIOR VIEW OF SECURED STORAGE ROOM; SHOWING EXTERIOR WINDOWS; SOUTHEAST CORNER OF MAIN SECTION OF BUILDING ON MAIN FLOOR; VIEW TO NORTHEAST.
- SD-21-W-21 INTERIOR VIEW OF UNOCCUPIED OFFICE SPACE LOOKING TOWARDS OPENING TO ANOTHER ROOM; SHOWING EXTERIOR WINDOW; NEAR NORTHEAST CORNER OF MAIN SECTION OF BUILDING ON MAIN FLOOR; VIEW TO WEST.
- SD-21-W-22 INTERIOR VIEW OF UNOCCUPIED OFFICE SPACE; SHOWING EXTERIOR WINDOWS; NEAR CENTER AND SOUTH SIDE OF MAIN SECTION OF BUILDING ON MAIN FLOOR; VIEW TO WEST.
- SD-21-W-23 INTERIOR VIEW OF ENTRANCE CORRIDOR LOOKING TOWARDS MAIN STAIRWAY; SHOWING UNOCCUPIED CORNER OFFICE SPACE AND ENCASED BULLETIN BOARDS; CENTER OF MAIN SECTION OF BUILDING ON MAIN FLOOR; VIEW TO NORTHEAST.
- SD-21-W-24 INTERIOR VIEW OF ENTRANCE CORRIDOR LOOKING DOWN EAST CORRIDOR; SHOWING UNOCCUPIED CORNER OFFICE SPACE AND STAIRS GOING DOWN TO LOWER FLOOR; CENTER OF MAIN SECTION OF BUILDING ON MAIN FLOOR; VIEW TO NORTHEAST.
- SD-21-W-25 INTERIOR VIEW OF UNOCCUPIED SPACE LOOKING TOWARDS ADJOINING ROOM; SHOWING ELECTRICAL WIRING AND EXTERIOR WINDOWS; NEAR SOUTHWEST CORNER OF MAIN SECTION OF BUILDING ON MAIN FLOOR; VIEW TO WEST.
- SD-21-W-26 INTERIOR VIEW OF UNOCCUPIED OFFICE SPACE; SHOWING EXTERIOR WINDOWS, CLOSED CLOSET, AND OPEN DOORWAY TO OTHER OFFICE; SOUTHWEST CORNER OF MAIN SECTION OF BUILDING ON MAIN FLOOR; VIEW TO SOUTHWEST.
- SD-21-W-27 INTERIOR VIEW OF UNOCCUPIED SPACE LOOKING TOWARDS TWO WAY GLASS OPENING; SHOWING RECESSED CEILING WITH COVE LIGHTING AND EXTERIOR WINDOWS; NEAR CENTER AND WEST SIDE OF WEST WING ON MAIN FLOOR; VIEW TO SOUTHWEST.

Ellsworth Air Force Base
Group Administration & Secure Storage Building
(Building No. 7810)
HABS No. SD-21-W
(Page 4)

- SD-21-W-28 INTERIOR VIEW OF UNOCCUPIED SPACE LOOKING TOWARDS CORRIDOR OPENING; SHOWING OPENED DOORWAY TO ANOTHER SPACE AND EXTERIOR WINDOWS; NEAR NORTH SIDE OF WEST WING ON MAIN FLOOR, VIEW TO SOUTH.
- SD-21-W-29 INTERIOR VIEW OF UNOCCUPIED OFFICE SPACE; SHOWING CLOSETS AND OPENED DOORWAY TO LOWER LEVEL CORRIDOR; SOUTHEAST CORNER OF LOWER FLOOR; VIEW TO NORTHWEST.
- SD-21-W-30 INTERIOR VIEW OF MECHANICAL ROOM; SHOWING MACHINERY; WEST END OF LOWER FLOOR; VIEW TO SOUTHWEST.

KEY TO PHOTOGRAPHS

Ellsworth Air Force Base
Group Administration & Secure Storage Building
(Building No. 7810)
HABS No. SD-21-W
(Page 5)



FIRST FLOOR PLAN

KEY TO PHOTOGRAPHS


Ellsworth Air Force Base

Group Administration & Secure Storage Building

(Building No. 7810)


HABS No. SD-21-W

(Page 6)



SECOND FLOOR PLAN

KEY TO PHOTOGRAPHS
Ellsworth Air Force Base
Group Administration & Secure Storage Building
(Building No. 7810)
HABS No. SD-21-W
(Page 7)



BASEMENT PLAN