

HABS
VA,
2-CHAR.V
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to
Monticello
.6 mile Northeast of State Route 53,
1.2 miles east of intersection with
State Route 20
Charlottesville vicinity
Albemarle County
Virginia

HABS No. VA-241

Photographs VA-241-1 through VA-241-8 previously transmitted to Library of Congress

Walter Smalling, Photographer March, 1978

- VA-241-9 WEST FACADE, FROM ACROSS GROUNDS
- VA-241-10 WEST FACADE, FROM THE NORTHWEST
- VA-241-11 WEST FACADE, FROM THE NORTHWEST (CLOSER VIEW)
- VA-241-12 WEST FACADE, FROM THE SOUTHWEST
- VA-241-13 WEST FACADE, FROM THE SOUTHWEST (CLOSER VIEW)
- VA-241-14 EAST FACADE, FROM ACROSS GROUNDS
- VA-241-15 EAST FACADE (CLOSER VIEW)
- VA-241-16 NORTH FACADE, FROM THE NORTHWEST
- VA-241-17 NORTH FACADE (ELEVATION)
- VA-241-18 DETAIL, WEST FACADE, PORTICO, FROM THE NORTHWEST
- VA-241-19 DETAIL, WEST FACADE, PORTICO, FROM THE SOUTHWEST
- VA-241-20 DETAIL, EAST FACADE, PORTICO, FROM THE SOUTHEAST
- VA-241-21 DETAIL, EAST FACADE, PORTICO, PEDIMENT
- VA-241-22 DETAIL, WEST FACADE, SOUTH END, WALL AND WATER TABLE
- VA-241-23 DETAIL, WEST FACADE, NORTH END, WALL AND CORNICE
- VA-241-24 DETAIL, BRICK WORK
- VA-241-25 SOUTH SERVICE WING
- VA-241-26 DETAIL, SOUTH SERVICE WING, ARCADE

VA-241-27 DETAIL, NORTH SERVICE WING , CISTERN COVER

VA-241-28 INTERIOR, ENTRANCE HALL, LOOKING EAST

VA-241-29 INTERIOR, ENTRANCE HALL, LOOKING NORTHEAST FROM BALCONY

VA-241-30 INTERIOR, ENTRANCE HALL, BALCONY, DETAIL OF CORNICE

VA-241-31 INTERIOR, ENTRANCE HALL, BALCONY, DETAIL OF CORNICE IN CORNER

VA-241-32 INTERIOR, DRAWING ROOM, DETAIL OF SOUTH WALL

VA-241-33 INTERIOR, DRAWING ROOM, WEST BAY

VA-241-34 INTERIOR, DINING ROOM, DETAIL OF NORTH WALL

VA-241-35 INTERIOR, MASTER BEDROOM, LOOKING SOUTHWEST

VA-241-36 INTERIOR, NORTHEAST BEDROOM

VA-241-37 INTERIOR, SOUTH STAIRCASE

VA-241-38 INTERIOR, DOME ROOM

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
VA
2-CHAR.V,
1-

ADDENDUM TO:

HABS No. VA-241
(p.3)

MONTICELLO
.6 mile Northeast of State Route 53,
1.2 miles east of intersection with State Rt. 20
Charlottesville vicinity
Albemarle county
Virginia

VA-241-1 through VA-241-38 were previously transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, March 1978

VA-241-39 (CT)	WEST FACADE FROM ACROSS GROUNDS
VA-241-40 (CT)	WEST FACADE FROM ACROSS GROUNDS
VA-241-41 (CT)	WEST FACADE, FROM THE SOUTHWEST
VA-241-42 (CT)	WEST FACADE, FROM THE SOUTHWEST
VA-241-43 (CT)	WEST FACADE, FROM THE NORTHWEST
VA-241-44 (CT)	WEST FACADE, FROM THE SOUTHWEST (CLOSER VIEW)
VA-241-45 (CT)	EAST FACADE, FROM ACROSS GROUNDS
VA-241-46 (CT)	EAST FACADE (CLOSER VIEW)
VA-241-47 (CT)	DETAIL, EAST FACADE, PORTICO, FROM THE SOUTHEAST
VA-241-48 (CT)	INTERIOR, DOME ROOM