

STATE	COUNTY	TOWN OR VICINITY
Virginia	James City County	Jamestown
INDEX NUMBER VA 48 JAM, 8-	MONUMENT ARCHITECTURAL REMAINS UNIT B Structure 110	
REPRESENTED IN NEGATIVE FILE	H.A.B.S. SURVEY NO. VA-444	<u>History:</u> The structure is dated approximately during the period
PUBLISHED PHOTOGRAPHS	1630 to 1650 on a basis of typology.	
PUBLISHED DRAWINGS	<u>Description:</u> A rectangular structure with inside measurements of 20'-4" wide and 21'-6" long. There is no evidence of interior partitions. The existing ruins consist of exterior brick wall foundations and a floor of red ceramic tiles. There are three fire-	
GPO 6-8369		boxes in the structure. These were undoubtedly used as furnaces. HISTORIC AMERICAN BUILDINGS SURVEY

3s
3p



A report on Structure 110, prepared by John L. Cotter, is on file with the U. S. Department of the Interior, National Park Service, Washington 25, D. C.

Author of Card

Charles W. Lessig, Architect

National Park Service

Washington, D. C.

September 24, 1956