

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS NO. CA-2289

Santos Farm
1481 Mowry Avenue
Fremont
Alameda County
California

HABS
CAL,
1-FREMO.
4-

Jack Schafer, Photographer; September 1989

- CA-2289-1 SANTOS FARM AND SURROUNDING CONTEXT, VIEW FROM ACROSS MOWRY AVENUE, FACING WEST. BAY AREA RAPID TRANSIT DISTRICT TRACKS CROSSING OVER MOWRY AVENUE AT LEFT
- CA-2289-2 VIEW FROM ACROSS MOWRY AVENUE, FACING WEST. QUONSET HUT AT LEFT, BARN AT CENTER, HOUSE AT RIGHT. MOWRY AVENUE IN FOREGROUND
- CA-2289-3 VIEW FROM ACROSS MOWRY AVENUE, FACING NORTHWEST. BARN AT LEFT, HOUSE AT RIGHT. MOWRY AVENUE IN FOREGROUND
- CA-2289-4 VIEW FROM ACROSS MOWRY AVENUE, FACING NORTHWEST. QUONSET HUT AND BARN
- CA-2289-5 GENERAL VIEW, FACING EAST
- CA-2289-6 VIEW OF ORCHARD, FACING EAST. SANTOS BARN, QUONSET HUT, AND STORAGE SHED IN BACKGROUND