

HAER
CAL
26-JUL.A.V,
ID -

HISTORIC AMERICAN ENGINEERING RECORD
INDEX TO PHOTOGRAPHS

**Rush Creek Hydroelectric System,
Worker Cottage (Building 105)
Rush Creek
June Lake Vicinity
Mono County
California**

HAER No. CA-166-D

Gregory L. O'Loughlin, photographer

August, 1997

- CA-166-D-1 EXTERIOR OVERVIEW OF NORTH END OF RUSH CREEK POWERHOUSE RESIDENTIAL COMPLEX SHOWING BUILDING 108 AT PHOTO RIGHT AND BUILDING 105 AT PHOTO CENTER BEHIND SWITCHRACKS AND TREE. POWERHOUSE IS AT EXTREME PHOTO LEFT. VIEW TO WEST.
- CA-166-D-2 EXTERIOR OF FRONT (EAST SIDE) OF BUILDING 105 SHOWING RECESSED PORCH FRAMED BY CRISS-CROSS WOOD BALUSTRADE, STONE FACING ALONG ORIGINAL PORTION OF HOUSE FRONT, AND ORIGINAL PLANK DOOR TO PORCH BASEMENT AT LOWER PHOTO CENTER. WELDED STEEL PORCH RAILINGS VISIBLE AT PHOTO LEFT CENTER WERE ADDED IN 1972. VIEW TO NORTHWEST.
- CA-166-D-3 EXTERIOR FRONT OF BUILDING 105 SHOWING OFFSET GABLE OVER RECESSED PORCH WITH RUSTIC STYLE DECORATIVE TREATMENT. VIEW TO SOUTHWEST.
- CA-166-D-4 EXTERIOR OF SOUTH END OF BUILDING 105 SHOWING TALL RUSTIC STYLE CHIMNEY WITH GABLE FRAME, METAL ROOF, AND CONCRETE WALKWAY AND STEP TO OPEN SIDE-ENTRY DOOR AT PHOTO CENTER. ORIGINAL DECORATIVE WOOD SHIP-LAP SIDING ON UPPER END GABLE HAS BEEN COVERED WITH ASPHALT SHINGLES. VIEW TO NORTH.
- CA-166-D-5 EXTERIOR OF NORTH END OF BUILDING 105 SHOWING 1946 BEDROOM ADDITION. BUILDING 108 IS VISIBLE AT EXTREME PHOTO LEFT. VIEW TO SOUTHEAST.

RUSH CREEK HYDROELECTRIC SYSTEM
WORKER COTTAGE (BUILDING 105)
HAER No. CA-166-D
INDEX TO PHOTOGRAPHS (Page 2)

- CA-166-D-6 INTERIOR OF BASEMENT UNDER KITCHEN SHOWING FINISHED SECTION. OPEN DOOR TO UNFINISHED SECTION IS VISIBLE AT RIGHT PHOTO CENTER. VIEW TO NORTHWEST.
- CA-166-D-7 INTERIOR BASEMENT UNDER KITCHEN SHOWING UNFINISHED SECTION. VIEW TO NORTHWEST.
- CA-I66-D-8 INTERIOR OF LIVING ROOM SHOWING 6-LIGHT FRONT ENTRY DOOR AND TWO 6-LIGHT OVER 1-LIGHT SASH WINDOWS TO PHOTO RIGHT OF FRONT DOOR OVERLOOKING PORCH. VIEW TO NORTHEAST.
- CA-166-D-9 INTERIOR OF LIVING ROOM SHOWING OPEN DOORWAY TO KITCHEN AT PHOTO LEFT CENTER, AND 6-LIGHT OVER 1-LIGHT SASH WINDOW ON REAR WALL AT PHOTO RIGHT. FIREPLACE ORIGINALLY OCCUPIED SPACE TO THE EXTREME PHOTO RIGHT OF SASH WINDOW ON THE REAR WALL. VIEW TO SOUTH.
- CA-I66-D-10 INTERIOR OF LIVING ROOM SHOWING OPEN PANEL DOOR TO BEDROOM NUMBER ONE AT PHOTO CENTER, AND SECOND 6-LIGHT OVER 1-LIGHT SASH WINDOW ON REAR WALL AT PHOTO LEFT. VIEW TO NORTH.
- CA-166-D-11 INTERIOR OF BEDROOM NUMBER ONE SHOWING OPEN DOOR FROM LIVING ROOM AT EXTREME PHOTO LEFT, OPEN DOOR TO WALK-IN CLOSET AT PHOTO LEFT CENTER, OPEN DOOR TO BATHROOM AT PHOTO CENTER, AND OPEN DOOR TO BEDROOM NUMBER TWO AT EXTREME PHOTO RIGHT. VIEW TO WEST.
- CA-I66-D-12 INTERIOR OF WALK-IN CLOSET SHOWING 1-LIGHT OVER 1-LIGHT SASH WINDOW ON REAR (WEST) WALL. VIEW TO SOUTHWEST.
- CA-166-D-13 INTERIOR OF BEDROOM NUMBER ONE SHOWING 6-LIGHT OVER 1-LIGHT SASH WINDOW ON EAST (FRONT) WALL. VIEW TO NORTHEAST.
- CA-I66-D-14 INTERIOR OF BATHROOM SHOWING REMODELED AND RELOCATED SHOWER/BATH ALONG NORTH WALL. VIEW TO NORTH.

RUSH CREEK HYDROELECTRIC SYSTEM
WORKER COTTAGE (BUILDING 105)
HAER No. CA-166-D
INDEX TO PHOTOGRAPHS (Page 3)

- CA-166-D-15 BATHROOM INTERIOR SHOWING 1-LIGHT OVER 1-LIGHT SASH WINDOW AT PHOTO CENTER, AND BUILT-IN CABINET OVER TOILET AT PHOTO LEFT. VIEW TO WEST.
- CA-166-D-16 INTERIOR OF BEDROOM NUMBER TWO SHOWING OPEN PANEL DOOR TO WALK-IN CLOSET AT PHOTO CENTER, OPEN PANEL DOOR FROM BEDROOM NUMBER ONE AT EXTREME PHOTO LEFT, AND 6-LIGHT OVER 1-LIGHT SASH WINDOW ON NORTH WALL AT PHOTO RIGHT. VIEW TO WEST.
- CA-166-D-17 INTERIOR OF BEDROOM NUMBER TWO WALK-IN CLOSET SHOWING 1-LIGHT OVER 1-LIGHT SASH WINDOW ON NORTH WALL. VIEW TO NORTH.
- CA-166-D-18 INTERIOR OF BEDROOM NUMBER TWO SHOWING 6-LIGHT OVER 1-LIGHT SASH WINDOW ON EAST (FRONT) WALL AT PHOTO LEFT, AND OPEN DOORWAY TO BEDROOM NUMBER ONE AT PHOTO RIGHT. VIEW TO EAST.
- CA-166-D-19 INTERIOR OF KITCHEN SHOWING UPDATED CABINETS, COUNTER TOP, SINK, AND FAUCET, AND ORIGINAL WOOD-FRAMED SLIDING GLASS WINDOW IN NORTH WALL AT PHOTO LEFT CENTER OVERLOOKING FRONT PORCH. VIEW TO NORTHEAST.
- CA-166-D-20 INTERIOR OF KITCHEN SHOWING UPDATED CABINETS AND ORIGINAL WOOD-FRAMED SLIDING GLASS WINDOWS OVER SINK. VIEW TO SOUTHEAST.
- CA-166-D-21 KITCHEN INTERIOR SHOWING OPEN 1-LIGHT SIDE-EXIT DOOR AT PHOTO LEFT AND BUILT-IN CABINETS AND WASHER/DRYER HOOKUPS ALONG WEST WALL AT PHOTO CENTER. VIEW TO SOUTHWEST.