

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
MD,  
19-LENTO. V,  
2-

Nevitt's St. Anne  
Leonardtown Vicinity  
St. Mary's County  
Maryland

HABS No. MD-873

Douglas Barber, Photographer 1972

- MD-873-1 PERSPECTIVE VIEW OF EAST GABLE END
- MD-873-2 PERSPECTIVE VIEW OF NORTH AND EAST ELEVATIONS
- MD-873-3 PERSPECTIVE VIEW FROM SOUTHWEST
- MD-873-4 SOUTH ELEVATION, DETAIL OF EAVES, SHOWING CONSTRUCTION
- MD-873-5 GROUND FLOOR, SOUTH ROOM, DETAIL OF WALL AND DOORWAY SHOWING EXPOSED POST
- MD-873-6 PARTITION BETWEEN NORTH AND SOUTH ROOMS, DETAIL OF ORIGINAL SPINE BEAM CONTAINING MORTICES FOR DOORWAY