

HABS
ORE
IS-MED,
ID-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Medford Service Center, Radio Shop (Building #2202)
1319 McAndrews Road
Medford
Jackson County
Oregon

HABS No. OR-160-D

Natalie Brown, Photographer

April 1993

- OR-160-D-1 VIEW OF EAST FRONT AND NORTH SIDE OF RADIO SHOP (BUILDING #2202) FACING SOUTHWEST. PHOTOGRAPH TAKEN FROM WITHIN BUILDING 2300; NOTE THE RECENT "C.C.C.-STYLE" PORGH DETAIL, ADDED IN 1980s.
- OR-160-D-2 VIEW OF BUILDING #2202 (EAST FRONT AND NORTH SIDE) SHOWING RADIO ANTENNAE.
- OR-160-D-3 VIEW OF CENTER OF EAST FRONT OF BUILDING #2202. NOTE "C.C.C./F.S. PINETREE" SYMBOL IN PEAK OF GABLE END.
- OR-160-D-4 VIEW OF WEST REAR AND SOUTH SIDE OF BUILDING #2202, FAGING NORTHEAST. (NOTE: UNTIL 1980s, LARGE POPLAR TREES GREW NEXT TO REAR OF BUILDING.)
- OR-160-D-5 VIEW OF INTERIOR OF NORTH PORTION OF BUILDING #2202, FACING NORTHWEST.
- OR-160-D-6 VIEW OF INTERIOR OF MIDDLE PORTION OF BUILDING #2202, FAGING EAST.
- OR-160-D-7 VIEW OF INTERIOR OF SOUTH PORTION OF BUILDING #2202, FACING SOUTH.

Note: All photographs are 8" x 10" enlargements from 4" x 5" negatives.