

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:
PEAR VALLEY
State Route 628 vicinity
Shadyside vicinity
Northampton County
Virginia

HABS VA-960

INDEX TO BLACK AND WHITE PHOTOGRAPHS

James W. Rosenthal, photographer, January 2011

VA-960-1	Perspective view looking from the northeast to the east (front) and north gable end
VA-960-2	Perspective view looking from the southeast
VA-960-3	Closer view looking from the southeast
VA-960-4	East (front) elevation, with scale
VA-960-5	Close perspective view looking from the northeast
VA-960-6	North elevation, with scale
VA-960-7	Perspective view of the north elevation looking from the northwest
VA-960-8	Detail view of the west elevation to show eaves
VA-960-9	Perspective view of the west elevation looking from the northwest
VA-960-10	West elevation, with scale
VA-960-11	Perspective view looking from the southwest
VA-960-12	South elevation, with scale
VA-960-13	Interior view, looking west
VA-960-14	Interior view, looking north to fireplace

PEAR VALLEY
HABS VA-960
INDEX TO PHOTOGRAPHS

- VA-960-15 Interior view, looking east
- VA-960-16 Interior view, looking south (note modern ladder in southeast corner in position of original stair)
- VA-960-17 Interior view, perspective view looking from the southwest to the northeast corner
- VA-960-18 Interior view, detail view in the southwest corner to show framing, note chamfer detail on the corner post and end girt
- VA-960-19 Interior view, detail view of the framing for a door in the west wall that shows a chamfered post and early plaster